

SND 4535 (Rev. 1/65)

GENERAL (Card No. 1)

SUPPLEMENTARY (Contd. No. 2)

PERSONNEL STATISTICS
(Card No. 3)

File Number	(b) (6)						Rank/Rate	Br Service	Age	Yrs Exper	Status	Position	In to Ind	Abandon A/C	Pilot Factor	Training Utilization	Instr. Card	Total Time All Models	All Models 3 months	All Series This Model	All Ser Mod 3 months	CY Landings	Instrument H	Min Hours	Total Time per or Holo	
03	ALVIS	J	H	2	1	L	J	A	G	22	1	3	3	4	0	7	9	9	0	7	-	0	5	0	9	9
04																										

CLOSED
 1 JAN 1967

IBM: PERSONNEL CODED ON REVERSE SIDE ☐

4 JAN 1967

CODED REVIEWED LOGGED PUNCHED VERIFIED

08 NOV 1966

CODE SHEET REVIEWED BY CLASS DESK ANALYST

712220

Date _____

12-13-66

400

(b) (6)

I D. Number	GCI	MODEL	FY	MODEL CODE
(b) (6)	00	-A4C	7	04

[illegible]

CPD 65

[illegible]

CNRD 65A

16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74
----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

CARD 658

06 MAR 1967

[illegible]

CARD 66

(b) (6)

I D. NUMBER	GCI	MODEL	FY	MODEL CODE
(b) (6)	00	-A4C	7	04

TYPE		WIND	WAVE	VIS.	AIR	WATER	ALERT	LOC	SURV	FACTORS	TRG	TRG	TRG	HISTORY		STATUS		REMARKS	
TYPE	TYPE	VEL	HEIGHT	IBILITY	TEMP	TEMP	FACTOR	SURV	FACTOR	(NO RECORD)	DATE	DATE	FACTOR	NO	DATE	NO	DATE	NO	DATE
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35
AC							EB	AD	V		PP	PP	PP						

CARD 67

[illegible]

TIME ALERT TO LOG.	PROB IN RTE.	FIL T O R S N	R E A S O N	TIME LOC To REH.	LOCATION MEANS	Loc. PROB	CURE SIG. PROB	T Y P E D I S C	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	RESCUE PROBLEMS	SURVIVOR PROBLEMS	SURV. COND	SURV. COND	TIME Rem. To Ass.	TOT TIME	PES ACC.	SIG OF IND	
16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36
01					0113				AC								AG	01	03	01

CARD 69

MAINTENANCE AND MATERIAL CODE SHEET (Narrative brief on reverse)

SND 4621 (Rev. 11/65)

MAINTENANCE AND MATERIAL CARD NUMBER 33				CARD COL.
PRIMARY INVOLVED MATERIAL COMPONENT		T 9 9 9 9		16-21
SECONDARY INVOLVED MATERIAL COMPONENT				24-29
POSSIBLE INVOLVED MATERIAL COMPONENT				32-37
SPECIAL DATA AND CONDITIONS		T 4 5		40-42
SPECIAL DATA AND CONDITIONS		T 1 5		44-46
SPECIAL DATA AND CONDITIONS		T 3 6		48-50
SPECIAL DATA AND CONDITIONS				52-54
SPECIAL DATA AND CONDITIONS				56-58
SPECIAL DATA AND CONDITIONS				61-63
FIRST MAINT FLT/SPEC COMPONENT				65-68
CARD NUMBER		3	3	79-80

MAINTENANCE AND MATERIAL CARD NUMBER 35				CARD COL.
POSSIBLE OR SECONDARY INVOLVED MATERIAL COMPONENT:				
MFG P/N				16-31
TOTAL HOURS				34-37
OVERHAUL ACTIVITY				39
NUMBER OF OVERHAULS				41
HOURS SINCE OVERHAUL				43-46
POWER PLANT MODEL NUMBER		J 6 5 W 1 6		49-56
POWER PLANT SERIAL NUMBER		6 1 2 3 3 2		58-64
DIR		2		68
CARD NUMBER		3	5	79-80

MAINTENANCE AND MATERIAL CARD NUMBER 34				CARD COL.
PRIMARY INVOLVED MATERIAL COMPONENT:				
MFG P/N				16-31
TOTAL HOURS		9 5 7		34-37
OVERHAUL ACTIVITY		9		39
NUMBER OF OVERHAULS		3		41
HOURS SINCE OVERHAUL		1 5 5		43-46
AIRCRAFT TOUR				48-50
AIRCRAFT FLIGHT HOURS SINCE ACCEPTANCE		1		52-54
AIRCRAFT FLIGHT HOURS SINCE LAST INSPECTION		1 5 5		56-58
DAYS SINCE LAST AIRCRAFT INSPECTION		8 9		61-63
TYPE LAST AIRCRAFT INSPECTION		4		65-68
MONTHS SINCE PAR/OVERHAUL		3		79-80
CARD NUMBER		3	4	79-80

CAUSE FACTORS	3			
COMPONENT NO. 1	T			
COMPONENT NO. 2				
DESIGN				

POSSIBLE CAUSE FACTORS			
COMPONENT			
DESIGN			

08 NOV 1966

FOR IBM

ACCIDENT DAMAGE									
ACCIDENT INJURY									
SPECIAL ATTN ("B")									
Model Code									

COORDINATOR	M&M CODING RECORD		
DIVISION OFFICER	DATE CODED	CODED BY	LOGGED
	10-4		

PUNCHED	VERIFIED
PUNCHED	VERIFIED

FOR M&M FILING ONLY			REPORT NUMBER
MODEL	SUNG	DATE	CUSTOMER

16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68

ACFT ON A CROSS

COUNTRY FLT FROM LEMORE CALIF TO ABILENE TEXAS. AFTER

COMPLETION OF INFLIGHT REFUELING IN ROUTE PLT INFORM-

ED OF WX FRONT IN HIS FLT PATH & ELECTED TO FLY

THROUGH IT. SOME ICING ON THE WIND SCREEN, BUT RPM &

DEAP REMAINED NORMAL. SHORTLY AFTER PLT OBSERVED A

FAINT HIGH PITCH SQUEAL BUT DID NOT ASSOCIATE THE

SQUEAL WITH THE ENG. THERE WERE NO VIB & INST REMAIN-

ED NORMAL. THERE WAS A BUILD UP OF THE SQUEAL AND A

MODERATE EXPLOSION WAS EXPERIENCED. ALL ELECT PWR WAS

LOST, RAT EXTENDED, ELECT PWR RESTORED, ENG INST RPM

A FEW READ ZERO. PLT MOVED THR BACK & FORTH BUT RE-

LIGHT WAS UNSUCCESSFUL. NO FIELD TO LAND IN SO PLT

ELECTED TO EJECT. THE EJECTION, SEAT SEPARATION AND

PARACHUTE OPENING WERE NORMAL. FAILURE ANALYSIS REVL'D

ENG/COMPRESS FAILURE DUE UNIDENTIFIED FOROBJ.

16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68

16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68

CARD NO.

70 68

3 6

3 7

3 8

3 9

4 0

4 1

4 2

4 3

4 4

4 5

4 6

4 7

4 8

4 9

5 0

5 1

5 2

5 3

5 4

5 5

5 6

5 7

5 8

5 9

70 68

NAVAL AVIATION SAFETY CENTER
NAVAL AIR STATION
NORFOLK, VIRGINIA 23511

112/kn
Ser 1519
22 December 1966

SPECIAL HANDLING REQUIRED IAW OPNAVINST 3750.6 SERIES
FOR OFFICIAL USE ONLY

From: Commander, Naval Aviation Safety Center
To: Commanding Officer, Attack Squadron ONE ONE TWO
Subj: VA-112 AAR ser 3-66A concerning A-4C BuNo 148567 accident
occurring 12 August 1966, pilot ALVIS

1. The subject report and all endorsements thereon have been reviewed. Commander, Naval Aviation Safety Center concurs with the comments and recommendations of the Aircraft Accident Board as modified by subsequent endorsers.
2. The cause of this accident has been recorded at the NAVAVNSAFECEN indicating MATERIAL (foreign object damage to engine compressor) as the single cause factor.

(b) (6)

By direction

Copy to:
NAVAIRSYSCOMHQ (AIR 404) (2)
COMNAVAIRPAC
COMSEIGHT
COMFAIRALAMEDA
COMCVW-11
NAVPLANTREPO LONG BEACH
CO NAVAERORECOVPAC
CO NAVWPNEVALFAC

FOR OFFICIAL USE ONLY

3750 7080
80/

29 NOV 1966

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH OPNAVINST 3750.6 SERIES

FIFTH ENDORSEMENT on VA-112 AAR ser 3-66A concerning A-4C BuNo 148567
accident occurring 12 August 1966, pilot ALVIS

From: Commander Naval Air Force, U.S. Pacific Fleet
To: Commander, U.S. Naval Aviation Safety Center

Subj: VA-112 AAR ser 3-66A

Ref: (b) OPNAVINST 3750.6E

1. Forwarded, concurring in the comments and recommendations of the
Aircraft Accident Board, as modified by the remarks contained in sub-
sequent endorsements.

2. The following administrative errors are noted:

a. The enclosures are not attached in the proper sequence as re-
ferred to in the account in accordance with paragraph 46 of reference
(b).

b. The first and second endorsements do not show complete copy
distribution in accordance with sub-paragraph 48h of reference (b).
By copy of this endorsement the Commanding Officer, NAWPNEVALFAC
Kirtland AFB and the Commanding Officer, ATKRON 112 are requested to
ensure complete copy distribution of the first and second endorsements
respectively.

(b) (6)

By direction

Copy to:
NAVAIRSYSCOMHQ
COMNAVAVNSAFECEN (2)
COMEIGHT
COMATKCARAIRWING 11
COMFAIRALAMEDA
CO ATKRON 112
NAVPLANTREPO LBEACH
CO AEROSPACE RECOVERY FACILITY
CO NAWPNEVALFAC

ORIGINAL

FFI-2/3750
Ser 301B/4635
1 Nov 1966

SPECIAL HANDLING REQUIRED IN ACCORDANCE
WITH ORNAV INSTRUCTION P3750.6 (Series)

FOURTH ENDORSEMENT on CO, ATKRON 112 AAR, serial 3-66A, concerning A4C,
BUNO 148567, Accident occurring 12 Aug 1966, Pilot ALVIS

From: Commander Fleet Air Alameda
To: Commander, U. S. Naval Aviation Safety Center
Via: Commander Naval Air Force, U. S. Pacific Fleet

Subj: ATKRON 112, AAR ser 3-66A; forwarding of

Ref: (a) CO, HAWWHEVAIFAC ltr FFL2/CSP:bcc 5000 Ser APP/1453 of
20 Oct 1966

1. Forwarded, concurring in the comments and recommendations of the
Aircraft Accident Board, and in the remarks contained in the preceding
endorsements.

2. Enclosure (1) to reference (a) concluded that the foreign object
might be from a coupling.

(b) (6)

Chief Staff Officer

Copy to:
CO, HAWWHEVAIFAC
NAVAVIRSYGUMHQ
COMNAVAVIRSAFECH (2) (Airmail direct)
COMELIGHT
COMNAVCAIRWING 11
CO, ATKRON 112
NAVFLATIREPO LONG BEACH
CO, HAVANORRECOVTAC

ORIGINAL

U. S. NAVAL WEAPONS EVALUATION FACILITY
Kirtland Air Force Base
Albuquerque, New Mexico 87117

FF12/CSP:bcc
5000
Ser APP/ 1453
20 October 1966

From: Commanding Officer, U. S. Naval Weapons Evaluation Facility
To: Commander, U. S. Naval Aviation Safety Center, U. S. Naval
Air Station, Norfolk, Virginia 23511

Subj: VA-112 Aircraft Accident Report 3-66A

Encl: (1) Metallurgical report on foreign object suspected of causing
engine failure on subject accident

1. The attached metallurgical report is forwarded for inclusion as enclosure (15) to subject Aircraft Accident Report.
2. Further investigation by the Aircraft Accident Investigation Board and by the Douglas Aircraft Company, Long Beach, has failed to reveal the nature or source of this foreign object.


R. W. JACKSON

Copy to:
ATKRON 112
CO Naval Aerospace Recovery Facility, El Centro, Calif.
COMATKCARAIRWING 11
COMEIGHT
COMFAIRALAMEDA
COMNAVAIRPAC
NAVAIRSYSOM
NAVPLANTREPO, DAC, Long Beach, Calif.

AVC 148567

Weapons Engineering Group, Code 331

Attn: (b) (6)

Weapons Engineering Group TEI 4763

23 September 1966

Unknown metal parts

PART NUMBER	SPECIFICATION	GRADE	CLASS
Engine serial 612332	AIRCRAFT MODEL	BUREAU NUMBER	
	A-4C J65-W16A		1148567

TEST PERFORMED

1. X-ray spectrographic analyses.

TEST RESULTS

1. Request from an accident investigation for the identification of the metal parts are shown in the Table I.

TABLE I

VA-112 ANK 3-66A
ENCLOSURE 116

SAMPLES	IDENTIFICATION NOMENCLATURE	IDENTIFICATION
1. Outer steel shell	- Steel Casing	- 431 Stainless steel
2. Steel washer	- Washer	- 431 Stainless steel
3. Aluminum ferrule	- Aluminum Insert	- Similar to 6061 T-4 Aluminum alloy
4. Welded material on washer	- Brazed Tubing	- Primarily copper with some silver

2. Conclusion: The evidence indicates that the parts might be from a coupling.

SPECIAL HANDLING REQUIRED IN ACCORD PARA 66 OPNAVINST 3750.6E

TESTED
/s/ H. IEE

APPROVED
/s/ P. G. SCHRADER

ENCLOSURE (15)

ORIGINAL


FF12/CVV-11/21:bp
3750
Ser: 463A
13 October 1966

THIRD ENDORSEMENT on VA-112 AAF ser 3-66A, 12 Aug 66, ALC BUONO 148567
Pilot ALVIS

From: Commander Attack Carrier Air Wing ELEVEN
To: Commander Naval Aviation Safety Center
Via: (1) Commander Fleet Air Alameda
(2) Commander Naval Air Force, U. S. Pacific Fleet

Subj: Attack Squadron ONE ONE TWO Aircraft Accident Report; forwarding of

1. Forwarded, concurring in the conclusions/recommendations of the board and former endorsements, pending proper identification of the foreign object by the supplemental report.
2. It is regretted that the forwarding of this endorsement was delayed due to my absence.



E. R. WILLIAMS

Copy to:
NAVAVNSAFECN
NAVAIRSYSCOMHQ
CO, NWEF
COM EIGHT
COMNAVAIRPAC
COMFAIRALAMEDA
NPRO DAC LBEACH
CO, NAVAERORELOV
CO, VA-112

ORIGINAL

VA-112/JHA/mls

3750

Ser: 712

26 September 1966

**SECOND ENDORSEMENT on VA-112 AAR ser 3-66A, 12 Aug 1966, AAC BuNo. 148567
Pilot ALVIS**

**From: Commanding Officer, Attack Squadron ONE ONE TWO
To: Commander, Naval Aviation Safety Center
Via: (1) Commander, Attack Carrier Air Wing ONE ONE
(2) Commander, Fleet Air Alameda
(3) Commander, Naval Air Force, Pacific**

Subj: Attack Squadron ONE ONE TWO Aircraft Accident Report Serial 3-66A

1. Forwarded.
2. All pilots of this squadron have been rebriefed on engine operating limitations and the importance of reporting any limitations exceeded. Maintenance personnel have been briefed on proper procedures for correcting discrepancies concerning engine limitations which have been exceeded.
3. NATOPS procedures concerning ejection altitudes have been reviewed with all pilots.
4. The importance of FOD prevention has been reemphasized to all pilots and maintenance personnel.
5. The Medical Officer's signature is now affixed to page 3 of OPNAV FORM 3750-1. The Medical Officer's Report was mailed to the senior member of the Accident Board at NWEF via Air Mail Special Delivery on 18 September 1966.
6. The pilot has not been involved in any previous accidents.
7. A COMNAVAIRPAC accident prevention survey was completed at this command on 14 July 1966.


J. H. ALVIS

**Copy to:
CO NWEF
COMKIGHT
BUWEP
NPRO DAC LBRACH
NAVAL AEROSPACE RECOVERY FACILITY**

FF12/AT:hnm

3750

Ser AA/ 4 1400

23 SEP 1966

FIRST ENDORSEMENT on VA-112 AAR ser 3-66A, 12 Aug 1966, A4C BuNo. 148567,
Pilot ALVIS

From: Commanding Officer, U. S. Naval Weapons Evaluation Facility,
Kirtland Air Force Base, Albuquerque, New Mexico 87117

To: Commander, Naval Aviation Safety Center

Via: (1) Commanding Officer, Attack Squadron One One Two
(2) Commander, Attack Carrier Air Wing One One
(3) Commander, Fleet Air, Alameda
(4) Commander, Naval Air Force, Pacific

Subj: Attack Squadron One One Two Aircraft Accident Report Serial 3-66A

1. Forwarded, concurring in the conclusions and recommendations of the Aircraft Investigation Board.

2. It is noted that the Medical Officer's Report is not attached to the basic correspondence and that the medical officer's signature is not affixed on page 3. The Medical Officer's Report will be forwarded upon receipt at this command. The statement of the Air Force Flight Surgeon who examined CDR ALVIS is considered acceptable although not signed by the attending physician.


R. W. JACKSON

Copy to:
COM EIGHT
NPRO DAC LBEACH
CO NAVAERORELOV

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6
SERIES

787

From: Commanding Officer, Attack Squadron ONE ONE TWO

3 OCT 1966

To: Commander, U S Naval Aviation Safety Center

Subj: Supplementary Accident Data concerning VA-112 AAR serial 3-66A,
A4C BUNO 148567 occurring 12 August 1966, Pilot ALVIS

submission of

Ref: (a) NASC ltr ser: 50/A34 of 19 SEP 1966

- Encl: (1) Supplementary Accident Data Form for subject accident pages 1
through 5
(2) Reproduction of subject pilot's log covering month of accident
and two (2) preceding calendar months
(X) ~~CONFIDENTIAL~~
(X) ~~CONFIDENTIAL~~

1. As requested by reference (a), the enclosures are forwarded.

J.H. Alves
J.H. ALVIS

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6
SERIES

SUPPLEMENTARY ACCIDENT DATA

In addition to answering the following questions, enclose a duplicate of the pilot's log covering the month in which the accident occurred as well as the preceding two calendar months.

1. Date of mishap: year 1966 month AUG day 12
2. Aircraft model A4C
3. Bureau Number of aircraft 148567
4. Reporting custodian VA-112
5. Pilot file number 521212
6. Branch of service: Marine _____ Navy X
7. Readiness Attack Carrier Air Wing (RCVW) trained? Yes X No _____
If Yes, date completed 7/28/65
RCVW Squadron VA-125, NAS LEMOORE, CALIF.
8. Percentage of training completed if in a formal training status NA
9. Length of time (mo.) in present squadron 12 1/2
10. Pilot currently qualified in following aircraft (model and series)
A4C


FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

11. a. Specify training time (hrs.) with reference to date of mishap as follows:

	WST		OFT		CPT		LINK
	This model	All other models	This model	All other models	This model	All other models	
Previous 12 months	NA	NA	2	0	0	0	0
Previous 6 months	"	"	2	0	0	0	0
Previous 3 months	"	"	2	0	0	0	0
Previous 1 month	"	"	0	0	0	0	0

If training time in this model during previous three months was less than 3 hours in Weapons Systems Trainer (WST), Operational Flight Trainer (OFT), or Cockpit Training (CPT), indicate reason by checking appropriate spaces in part b.

b.	WST	OFT	CPT	LINK
(1) Pilot deployed	NA			
(2) Trainer not in area (station _____)				
(3) Down for maintenance		X		
(4) Not available due to trainer schedule		X		
(5) Lack of trainer personnel				
(6) Not available due to pilot's schedule		X		X
(7) Other reasons (specify): _____ _____				

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY

**SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6
SERIES**

12. If flight was a maintenance test flight, was pilot designated by Commanding Officer as qualified maintenance test pilot? Yes ☐ No ☐
Flight was not a test flight; however, pilot is designated test pilot
13. Commanding Officer's rating of pilot's ability: Superior ☒ pilot
Average ☐ Below Average ☐
14. Length of time (mo.) Commanding Officer
- a. Has been aboard 12 1/2
- b. Has been in command of this squadron (1)
15. Estimate of total time (hrs.) involved in accident investigation by:
- a. Accident board members 738
- b. Wreckage recovery and salvage 10 (10 man working party)
- c. Supporting Personnel 320 (USAF Air Police for security)
16. Best estimate of operation and maintenance funds expended for investigation and salvage (e.g. civilian salaries, O&R cost, equipment rental, etc.) \$ Unknown,
U.S. Air Force equipment, vehicles, etc. utilized. O & R cost unknown.
Attach itemized breakdown.
17. Did funding cause a delay in wreckage recovery? Yes ☐ No ☒
If Yes, how long? ☐ (days)
18. Was equipment for wreckage recovery adequate? Yes ☒ No ☐
If No, list deficiencies. _____

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

19. Number of accident board members 5
20. Specify number of accident board members who have attended the following schools :
- a. Safety Officer's School, USC 0
 - b. Safety Officer's School, Monterey 0
 - c. Safety Center 5-day ASO School 1
 - d. Monterey Baccalaureate Curriculum Safety Course 0
 - e. _____
 - f. None of the above _____

21. Specify by checking if the:

	Manufacturer's Technical Reps were			Manufacturer's Engineers were		
	<u>Requested</u>	<u>Available</u>	<u>Utilized</u>	<u>Requested</u>	<u>Available</u>	<u>Utilized</u>
Airframe	<u>Yes</u>	<u>Yes</u>	<u>Yes</u>	<u>No</u>	<u>Yes</u>	<u>No</u>
Engine	<u>Yes</u>	<u>Did not arrive due to transportation difficulty</u>		<u>No</u>	<u>UNK</u>	<u>No</u>
Other	_____	_____	_____	_____	_____	_____

22. Was pre-accident plan adequate? Yes X No _____

FOR OFFICIAL USE ONLY

**SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6
SERIES**

Yes X No

COMMENTS:

The majority of this Accident Board's training consisted of experience on previous Accident Boards.



factors similar to those associated with this mishap? Yes No **X**

COMMENTS:

FOR OFFICIAL USE ONLY

MONTH **JUNE 1966** YEAR **1966**

DAY	AIRCRAFT		TIME OF FLIGHT CODE	PILOT TIME			SPECIAL CREW TIME
	MODEL	SERIAL NUMBER		TOTAL PILOT TIME	PILOT	CO-PILOT	
1	A4C	148567	1A71	1.6	1.6		
1	"	147828	1A3	0.6	0.6		
1	"	147688	1A71	1.8	1.8		
2	"	147714	1A71	2.1	2.1		
3	"	147749	1A4	1.6	1.6		
3	"	147749	1A4	0.2	0.2		
3	"	147749	1A4	0.8	0.8		
12	"	147783	1A13	0.9	0.9		
13	"	147688	1A71	0.5	0.5		
13	"	147749	1A71	0.9	0.9		
14	"	147783	1A71	0.7	0.7		
14	"	147783	1A71	0.8	0.8		
15	"	147492	1A71	0.7	0.7		
16	"	148567	1A71	1.0	1.0		
17	"	147783	1A71	0.8	0.8		
17	"	147828	1A71	0.8	0.8		
18	"	147783	1A71	0.9	0.9		
20	"	147714	1A01	1.0	1.0		
20	"	147783	1A01	0.8	0.8		

TOTAL THIS PAGE

18.5 18.5

BROUGHT FORWARD

3382.4

320.3 315.8 4.5

TOTAL TO DATE

*See page 2 for codes.

TOTAL ACCUM PILOT TIME

TOTALS, THIS FISCAL YEAR

CODES: A-Automatic
C-CCA
1-ADF
2-GCA
1-ILS
1-LF range
2-ORNI
2-Radar
1-TACAN
2-Sound
1-Jm

DEPENDENT TIME		HIGHT TIME	LANDINGS		CATER	REMARKS
ACT	SM		CARRIER	SEA/LAND		
			1			
				10		
0.2	0.3	1.8		1	2 R	
				1	2 R	
			12			2 MX-76
			11			NAC + CV-20
				1		CV-20
0.2				1	1 1 6 5	CV-20 + NAC
				1		NAC - NFA
				1		
				1		6 MX-76
				1		100 - 80 MM
				1		6 MX-76
				1		100 - 20 MM
				1		6 MX-76
				1		30°/45°
				1		6 MX-76
				1		3/30°/3/45°/10°
				1		6 MX-76
				1		2 - 2.75" FFA
				1		
				1		4 MX-76
				1		2 MX-106

0.2 0.5 1.8 23 10 16 2

17.3 13.2 59.4 18 12255 55 13

CERTIFIED RECORD

Pilot

Approved

C.O. or authorized deputy

TOTALS, THIS FISCAL YEAR

Pilot time report submitted through last day of month.

MONTH JUNE YEAR 1966

DAY	AIRCRAFT		KIND OF FLIGHT CODE	PILOT TIME				SPECIAL CREW TIME
	MODEL	SERIAL NUMBER		TOTAL PILOT TIME	PILOT	CO-PILOT	A/C COMB.	
	BROUGHT FORWARD			18.5	18.5			
21	A4C	147714	1A75	1.0	1.0			
21	"	147783	1A75	1.0	1.0			
22	"	147714	1A75	1.1	1.1			
22	"	147688	1A71	0.9	0.9			
23	"	148567	1A71	0.9	0.9			
23	"	148567	1A71	1.3	1.3			
23	"	148567	1A04	0.9	0.9			
24	"	147783	1A04	0.6	0.6			
24	"	147783	1A15	0.7	0.7			
28	"	147796	1A03	2.5	2.5			
29	"	147796	3A71	1.8	1.8			
29	"	147796	1A03	2.5	2.5			
30	"	147833	1A15	2.8	2.8			
TOTAL THIS PAGE				36.5	36.5			
BROUGHT FORWARD		3382.4	320.3	315.8	4.5			
TOTAL TO DATE		3418.9	356.8	362.3	4.5			
*See page 2 for codes.		TOTAL ACCUM PILOT TIME	TOTALS THIS FISCAL YEAR					

MODES		9-ADF		1-LF range		7-TACAN	
8-Automatic		8-GCA		8-OMNI		8-Simulated	
E-CCA		1-ILS		8-Radar		1-Jet	
INDEPENDENT TIME		LANDINGS		SPECIAL		REMARKS	
ACT	Sim	Height	CASUALTY	E	SEA/LAND	U	REMARKS
0.2	0.5	1.8	2 3	10	16	2	3 MK-76
							2 MK-76
							2 MK-76
							2 MK-76
							4 MK-76
							2 MK-76
							2 MK-76
							6 MK-76
							3 MK-76
							4 MK-76
							2 MK-106
							2 MK-76
							1 MK-106
							NFL-NLC
							NLC DROP
							6 MK-76
							3 MK-76
							1 MK-76
							4/5
0.2	0.9	3.6	2 3	10	29	2	1 MK-76
17.3	13.2	57.4	4 6	122	55	4	1 MK-76
17.5	14.1	63.0	4 6	122	55	4	1 MK-76
TOTALS THIS FISCAL YEAR		TOTALS THIS FISCAL YEAR					

Please return report submitted through (or by mail) 1 day of this month.

CHECKED A CORRECT RECORD

Pilot

Approved

() or authorized deputy

Discussion

JULY

59.20

1966

DAY	AIRCRAFT		SINCE PILOT CODE	PILOT TIME			A/E COMPS	SPC- CIR COW TIME
	MODEL	SERIAL NUMBER		TOTAL PILOT TIME	TIME PILOT	CO- PILOT		
1	A4C	147833	1A4	1.5	1.5			
2	"	147472	1A	2.4	2.4			
11	"	149489	1A15	2.2	2.2			
12	"	147749	1A24	2.4	2.4			
13	"	147796	3A25	2.0	2.0			
15	"	148567	1A15	2.0	2.0			
18	"	147796	1A11	1.9	1.9			
20	"	147749	1A12	2.1	2.1			
22	"	147796	1A16	1.0	1.0			
22	"	147796	1A14	0.8	0.8			
28	"	147783	3A13	2.1	2.1			
TOTAL THIS PAGE				20.4	20.4			
BROUGHT FORWARD				3418.9	-	-		
TOTAL TO DATE				3439.3	20.4	20.4		
*See page 2 for codes.				TOTALS, THIS FISCAL YEAR				

0000 2-Automatic
6-CCA

○ —ADP
 ● —GCA
 I —ILS

1 = LF range
 ● = CHN1
 0 = Roder

1 - TACAN
2 - Simulated
3 - JPL

DISTURBANCE TIME		HOURS TIME	LANDINGS				NO. OF CARRIAGES	REMARKS
ACT	END		CARRIAGES	W	SEA / LAND			
	0.2				1	1 4 3	1.00-06 30	
					1	1 4 3		
	0.2				1	1 4 3	1.00-06 1.5	
					1		BARAA (2.0)	
		2.0			1		BARAA (1.5)	
	0.2				1	1 4 3	1.00-06 1.5	
					1	2 4 3	BARAA (0.2)	
					1	2 4 3		
	0.2				1	1 4 3	1.00-06 1.5	
0.3					1	1 4 3		
	0.2				1	1 4 3		
		2.1			1			
0.3	1.0	4.1			11			
-	-	-			-			
0.3	1.0	4.1			11			
TOTALS THIS FISCAL YEAR								

DUPLICATE

USN

(b) (6)

LEAK

CERTIFIED A
CORRECT RECORD

Pick

Approved

C.O. or authorized deputy

Pilot time report submitted through last 1st _____ day of this month, entered by _____ (month, day)

MONTH **AUGUST** YEAR **1966**

DAY	AIRCRAFT		KIND OF FLIGHT	PILOT TIME				SPECIAL CIRCUMSTANCES
	MODEL	SERIAL NUMBER		TOTAL FLIGHT TIME	PILOT	CO-PILOT	A/E COMB.	
2	A4C	147783	1A71	1.6	1.6			
3	"	147796	3A71	2.0	2.0			
4	"	145077	1A14	1.0	1.0			
5	"	147783	1A71	1.4	1.4			
9	"	147783	1A7	1.4	1.4			
10	"	147783	1A7	1.6	1.6			
11	"	147783	3A15	1.9	1.9			
11	"	150385	1A15	1.8	1.8			
12	"	147783	1A15	1.7	1.7			
12	"	148567	1A11	2.2	2.2			
17	"	147714	1A15	2.3	2.3			
18	"	145077	3A15	1.8	1.8			
19	"	147714	1A15	1.7	1.7			
22	"	147674	1A11	1.9	1.9			
23	"	148589	3A13	0.6	0.6			
23	"	148589	3A13	0.5	0.5			
24	"	147783	3A13	0.5	0.5			
24	"	147783	3A13	0.5	0.5			
25	"	147783	3A13	0.5	0.5			
25	"	147783	3A13	0.5	0.5			
TOTAL THIS PAGE				27.4	27.4			
BROUGHT FORWARD		3439.3	20.4	20.4				
TOTAL TO DATE		3466.7	47.8	47.8				
*See page 2 for codes.		TOTAL ACCUM. PILOT TIME	TOTALS, THIS FISCAL YEAR					

CODES: 1 - Automatic 2 - CCA		1 - ADF 2 - GCA 3 - ILS	1 - LF range 2 - OMNI 3 - Radar	1 - TACAN 2 - Simulated 3 - Jet						
DEPARTURE TIME		HIGHT TIME	LANDINGS					STD INST. APP. COMPLETED	REMARKS	
ACT	ENR		CARRIER			SEA/LAND	CAT			
			1	2	3	4	5	6	7	8
	0.2					1		1	A	S 2/20'
	0.2	2.0				1		1	A	S 5100' BULLPUP
	0.2					1		1	A	S 2 REV PLUGS
	0.2					1		1	A	S 6000-76 30'
	0.2					1		1	A	S .5 D 6000-76
	0.2					1		1	A	S 1 DAY 1 WET 1-50'
	0.2					1		1	A	S 1 BULLPUP
	0.2					1		1	A	S 1 DAY 4 WET
	0.4	1.9				1		2	A	S 1 BULLPUP
	0.2					1		1	A	S 6000 0.6
	0.2					1		1	A	S 6000 (1.5)
	0.2					1		1	A	S 6000 (0.5)
0.3										
	0.2					1		1	A	S 6000 (1.0)
		1.8				1		1	A	S 6000 (1.2)
	0.2					1		1	A	S 6000 (0.5)
	0.5	0.3				1		1	A	S
		0.5				5				
		0.5				7				
		0.5				6				
		0.5				8				
		0.5				6				
		0.5				6				
0.3	2.9	9.0				38	14			(b) (6)
0.3	1.0	4.1				-	11			
0.6	3.9	13.1				36	25			
TOTALS, THIS FISCAL YEAR										
Pilot time										
Approved										
() or authorized deputy										

PART I GENERAL

SECTION 4. IDENTIFICATION	1. AIRCRAFT ACCIDENT BOARD APPOINTED BY CO,		2. SERIAL NO.		3. DTG (LOCAL) OF MISHAP		4. MODEL AIRCRAFT		5. BUREAU NUMBER	
	Naval Weapons Evaluation Fac		VA-112,3-66A		121757T Aug		A-4C		148567	
	6. TO: Commander, Naval Aviation Safety Center				7. LOCATION OF MISHAP				10. DAMAGE	
					4.3 NM NW of Melrose, N.M.				ALPHA	
	8. VIA:		9.		11. TIME OF DAY		12. TIME IN FLIGHT		13. FLIGHT CODE	
	CO, USNWEF				Day		2+13		1A2	
	CO, ATKRON ONE ONE TWO				14. CLEARED					
COMATECARAIRWING ONE ONE				FROM NAS Lemoore, Cal. TO Dyess AFB, Texas						
COMFAIR ALAMEDA				15. TYPE CLEARANCE		16. AIRSPEED		17. A/C WEIGHT		
COMNAVAIRPAC				IFR		250 KIAS "P"		14,300 lb		
18. BRIEF DESCRIPTION OF MISHAP				19. ELEVATION AT TIME OF MISHAP						
Flameout at FL330, 2 unsuccessful relights, ejection.				FL330				TERRAIN 29,000 ft		
20. LIST MODEL, BUILD, REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete OPRAT Form 3750-1 for each A/C)										
NA										

FACTOR		FACTOR		FACTOR	
1.	PILOT ERROR IN TECHNIQUE/JUDGMENT	9.	SERVICING PERSONNEL	17.	WEATHER
2.	PILOT DEVIATION FROM NATOPS PROCEDURES	10.	LANDING SIGNAL OFFICER	18.	DESIGN AIRCRAFT
3.	PILOT INCORRECT OPERATION OF A/C SYSTEM	11.	OTHER PERSONNEL (Specify)	19.	DESIGN CREW EQUIPMENT
4.	PILOT OTHER (Specify)	12.	ADMINISTRATIVE	20.	DESIGN OTHER (Specify)
5.	CREW	13.	FACILITIES-RUNWAY OVERRUN TAXIWAY FLIGHT DECK	21.	ROLLING/PITCHING DECK ROUGH SEAS
6.	MAINTENANCE PERSONNEL	14.	FACILITIES-NAV AIDS LANDING AIDS (CCA, CCA, ILS, MIRROR)	22.	MATERIAL FAILURE/MALFUNCTION
7.	MAINTENANCE SUPERVISORY PERSONNEL	15.	FACILITIES-CATAPULT ARRESTING GEAR (Ship or field)	23.	UNDETERMINED
8.	SUPERVISORY OTHER (Specify)	16.	FACILITIES OTHER (Specify)	24.	OTHER (Specify)
				S	FOD (Compressor Fail)

1. NAME (LAST, FIRST, & MIDDLE INITIAL)	2. GRADE	3. SERVICE NO.	4. BRANCH OF SERVICE	5. AGE	6. RANK	7. BILLET	8. POSITION	9. SIGNATURE
PILOT (AT CONTROLS AT TIME OF MIDSHIP)								
ALVIS, JOHN H.	CDR	(b) (6)	USN	(b) (6)	15	CO	CKPT	G
CD-PILOT (IDENTIFY & SIGNIF. SEPARATE PAGE 1)								
NA								

ITEM		ITEM	
11.		17.	
ALL MODELS	3457	CV LANDINGS DAY/NIGHT	ALL 385/107
12.			IN MODEL 280/71
ALL MODELS IN LAST 12 MONTHS	358	18.	
13.		FCLP LANDINGS LAST 6 MONTHS DAY/NIGHT	ALL 10/0
ALL MODELS IN LAST 3 MONTHS	74		IN MODEL 10/0
14.		19.	
ALL SERIES THIS MODEL	A/C 1270	INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED	ALL 1/4
	OFT/OPT 11/2		IN MODEL 1/4
15.		20.	
ALL SERIES THIS MODEL	A/C 358	NIGHT HOURS LAST 3 MONTHS	ALL 10
LAST 12 MONTHS	OFT/OPT 2/0		IN MODEL 10
16.		21. TOTAL HOURS IN JETS (if jet mishap)	
ALL SERIES THIS MODEL	A/C 74	HELOS (if helo mishap)	JET 1933
LAST 3 MONTHS	OFT/OPT 2/0	22.	
		LAST PRIOR FLIGHT ALL SERIES THIS MODEL	DATE 8/12/66
			DURATION 1.7
23.		24.	
DATE/GRADE LAST NATOPS STANDARDIZATION CHECK	SAT 5/27/66	TYPE INSTRUMENT CARD	SPEC

[illegible]

PART II. MAINTENANCE, MATERIAL, AND FACILITIES DATA

A. A/C HISTORY		1. DATE OF MANUFACTURE	2. FLIGHT HRS. SINCE ACCEPTANCE	3. NO. OF PAR/OVERHAUL	4. MONTHS SINCE LAST PAR/OVERHAUL	5. FLY. HRS SINCE LAST PAR/OVERHAUL	6. LAST/PAV OVERHAUL ACTIVITY	7. TYPE OF LAST CHECK PERFORMED	8. FLIGHT HOURS SINCE LAST CHECK	9. DAYS SINCE LAST CHECK
		9/12/61	1589.9	3	3	155.2	ALA	MAJOR	155.2	83

B. ENGINE HISTORY		1. ENGINE MODEL	2. ENGINE SERIAL NUMBER	3. FLIGHT HRS. SINCE ACCEPTANCE	4. NUMBER OF OVERHAULS	5. WAS DIR. REQUESTED?	6. FLY. HRS SINCE LAST OVERHAUL	7. LAST OVERHAUL ACTIVITY	8. TYPE OF LAST CHECK PERFORMED	9. FLIGHT HOURS SINCE LAST CHECK	10. DAYS SINCE LAST CHECK
(1)		J65W16	612332	956.8	3	YES	155.2	ALA	MAJOR	155.2	83
(2)											
(3)											
(4)											

C. COMPONENT HISTORY		1. COMPONENT INVOLVED NOMENCLATURE	2. MANUFACTURERS PART NUMBER	3. TOTAL HRS ON PART	4. NO. OF OVERHAULS	5. HOURS SINCE LAST OVERHAUL	6. OVERHAUL ACTIVITY	7. WAS DIR. REQUESTED?	8. SER. NO. FLR/RMP/FLR
(1)									
(2)									
(3)									
(4)									

D. INCIDENTS & GROUND ACCIDENTS		1. PARTS REPAIRED	3. DIRECT MANHOURLS INVOLVED	2. PARTS REPLACED	
		PART NUMBER	NOMENCLATURE	PART NUMBER	NOMENCLATURE

JET ENGINE FLAMEOUT (Include intentional securing to prevent engine damage)									
AT TIME OF FLAMEOUT	1. ALTITUDE	2. IAS	3. RPM	4. TOT.	5. MANEUVER AT TIME OF FLAMEOUT	6. FUEL FLOW	7. ATTITUDE	8. G FORCES	9. RELIGHT
FL330	250KT	96%	610°C	Level Flight	UNK	Level	1G	<input checked="" type="checkbox"/> ATTEMPTED <input type="checkbox"/> ACCOMPLISHED	15,000 Ft
									20,000 Ft
									190 KTS
									6
									2
13. ENGINE SYMPTOMS									
14. CAUSE OF SYMPTOMS									

RECIPROCATING ENGINE FAILURE									
17. ALTITUDE	18. IAS	19. ATTITUDE	20. RPM	21. MAP	22. TORQUE/SHHP	23. FUEL FLOW PRESSURE	24. OIL PRESSURE	25. ENGINE SYMPTOMS	26. CAUSE OF SYMPTOMS

F. OTHER REPORT	
1. AMPLUR SERIAL NUMBER	
2. DIR MESSAGE REQUEST DATE-TIME-GROUP 181440Z AUG 66	
3. OTHER NAVAIRSYSCOMREPAC 222223Z Aug 66 Priority DIR Control #3047-67	
4. ATKRON ONE ONE TWO 130712Z Aug 66 Prelim & Supp Mst Rpt of A/C Accident	
5. NWEF 192041Z Aug 66 Investigation Extension	

1. EQUIPMENT INVOLVED <input type="checkbox"/> CATAPULT <input type="checkbox"/> ARRESTING GEAR		2. PRESSURE SETTING	3. WIND OVER DECK	4. RELATIVE WIND	5. APPROACH/END SPEED
6. MARK NUMBER	7. MODEL NUMBER	8. LOCATION ON SHIP	9. LAUNCHING BRIDLE AND BRIDLE ARRESTER		
10. CATAPULT/ARRESTING GEAR BULLETINS OR NOTIFICATIONS USED					

11. This portion shall be completed whenever (1) an aircraft accident involves arresting gear barrier and/or barricade equipment, or (2) an aircraft accident involves malfunctioning of arresting gear, barrier and/or barricade equipment. Incidents or routine damage to cables, windings and other expendable equipment need not be reported herein.

ENGAGED	12. DECK RUNOUT (FEET)	13. RAM TRAVEL (INCHES)	14. CONTROL VALVE SETTINGS		15. ACCUMULATOR PRESSURE (PSI)	16. COMMENTS (for cable failures specify no. landings and months in service)
			CONSTANT PRESSURE DOWN (P.S.I.)	CONSTANT RUN-OUT (WT. LBS.) Ratio		
DECK PENDANT						
DECK PENDANT						
BARRIER/BARRICADE						

FOR ACCIDENTS ABOARD CARRIERS (Complete on pilot)						
1. DATE DEPLOYED COMUS		3. DAY HOURS/LANDINGS SINCE DEPLOYMENT		4. DAY HOURS/LANDING LAST 30 DAYS		
2. NO. DAYS OPERATING PERIOD						
5. INST. HOURS LOADED SINCE DEPLOYMENT ACTUAL/SIMULATED		6. NIGHT HOURS/LANDINGS SINCE DEPLOYMENT		7. NIGHT HOURS/LANDINGS LAST 30 DAYS		

WEATHER AT SCENE OF MISHAP						
1. CEILING	2. VISIBILITY	3. RELATIVE WIND DIRECTION AND VELOCITY		4. TEMPERATURE RUNWAY OUTSIDE AIR	5. DEN POINT	6. ALTIMETER SETTING
7. OTHER WEATHER CONDITIONS (Winds etc./, icing level, sea state, density altitude, as appropriate)						

PART III ADDITIONAL INFORMATION			
PART	SECTION	ITEM	REMARKS
			<div>1. COPY DISTRIBUTION</div> <div>2 CC NAVYNAFSEC DIRECT (AAR)</div> <div>1 CC BUPERS DIRECT (AAR)</div> <div>1 CC CO, NWEF</div> <div>1 CC COM EIGHT</div> <div>1 CC COMNAVIAIRPAC</div> <div>1 CC ATKRON ONE ONE TWO</div> <div>1 CC COMATKCARAIRWINGONE</div> <div>1 CC COMFAIR ALAMEDA</div> <div>1 CC NPRO DAC LREACH</div> <div>1 CC CO NAVAERORELOW</div>

COST DAMAGE TO:		1. GOVERNMENT PROPERTY	2. PRIVATE PROPERTY	3. DATE SUBMITTED TO GS
None		None	None	SEP 1 1966

PART IV SIGNATURES OF THE BOARD			
1. SENIOR MEMBER	2. MEMBER	3. MEMBER	4. MEMBER
CDR (b)(6) USN, NWEF	NWEF A/C Projects Off UNIT BILLET	LCDR (b)(6) USN	CVW-11 Safety Off. UNIT BILLET
LT (b)(6) USN, CVW-11 Lt Surg.		LCDR (b)(6) USN	NWEF Projects Division Off. UNIT BILLET

* When preparing Incident and Ground Accident reports, items indicated by an asterisk in the upper right hand corner must be filled in. Other items considered appropriate should also be filled in.

5. BY (b)(6) USN NWEF Maint. Control Off.

PART V - THE ACCIDENT

At 1544T, 12 August 1966, CDR J. H. ALVIS, pilot, departed NAS Lemoore, California in A-4C BUNO 148567 on an instrument navigation flight to Dyeas AFB, Texas. An instrument flight plan was filed with provisions for enroute air refueling. Flight level 330 was assigned. Following completion of air refueling at FL290 in the vicinity of Needles, California, FL330 was resumed. The flight progressed without incident until passing Albuquerque, New Mexico. Radar fixes from ABQ Center showed an ave. ground speed of 435 KTS between Prescott and ABQ. The airplane was level at FL330 with an IAS of 250 KTS. Eight minutes after passing ABQ, the air route traffic controller at ABQ advised the pilot of a precipitation area directly ahead at about 25 miles with tops reported at FL450 and gave an F-4 pilot report of moderate to severe turb at FL330, 25 miles south of CDR ALVIS' course. The controller then queried the pilot concerning a vector south of course. Following inflight evaluation, the pilot elected to remain on course. The pilot then queried the center controller concerning the width of the precipitation area and was informed that the band was oriented east-west and that he would clear the area on his projected course in about 25 miles. As the airplane entered the precipitation area, the auto-pilot was disengaged, and pilot heat was actuated "on". Light turbulence was encountered and visible rime icing appeared on the wind screen. The pilot monitored engine instruments commencing with the weather penetration, noting steady indications of 94% RPM, EGT of about 580°C, last noted oil pressure was steady 34 psi. The pilot added pwr to 96%, and the EGT stabilized at 610°C. Oil pressure not specifically noted. The pilot then heard a noise he described as a faint hi-pitched squeal. The engine inst. were normal. The squeal increased in intensity and was followed by a moderate explosion, aircraft yaw, and total loss of electrical power. Following extension of the emergency generator, the pilot regained radio contact with ABQ Center and stated he had experienced an engine explosion, was passing 27,500' and requested a vector to any field within 30 miles. The controller responded with vector information to Cannon AFB, 090°, 47 miles. The pilot established a glide at 210 KTS, turned to the vector heading and prepared for a relight attempt at 20,000'. The pilot broke into the clear at 25,000'. The relight attempt at 20,000' was unsuccessful. RPM, EGT, and oil pressure indicated zero. A second relight attempt was conducted at approximately 15,000' with no response. Following the engine explosion, the fuel flowmeter indicated 1500 pph - no change was noted during relight attempts nor power lever movement.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

8 8

Passing 12,500', vector information to Cannon was 090°/25 miles. An Air Force F-4C listening on the common control frequency offered assistance and was subsequently vectored to the stricken aircraft. Passing approximately 10,000' with Cannon AFB 20 miles distant, the pilot reported he would not wake the field. He cautioned the F-4 pilot to stay clear while he jettisoned his tanks and announced his decision to eject. At a radar position 18 miles west of Cannon AFB and 38 secs after passing an indicated altitude of 7000', the pilot ejected about 12-1500' above ground level, using the face curtain. The aircraft was trimmed nose down and following ejection assumed an increasing dive angle impacting in an open field at about 60°, exploded and disintegrated. The pilot reported the ejection sequence as normal and he landed uninjured in an adjacent open field about 1 mile NNW of the crash site. He was picked up by a local resident, driven to the crash site, then transferred via rescue helo to Cannon AFB. The Melrose Fire Department was the first facility at the scene and put out grass fires surrounding the impact position. They were subsequently relieved by a fire party from Cannon AFB some 23 miles distant by road.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

PART VI - DAMAGE TO AIRCRAFT

The exact damage occurring in the engine prior to ground impact is not conclusive, but certain damage is apparent based on the DIR investigation (enclosure (10)). The first through third compressor rotor and stator blades showed evidence of rotational damage incurred by a foreign object. The fourth through seventh rotor blades (aluminum) were wiped out and appeared to have vaporized and were deposited on the turbine stator and rotor blades. (See heavy metallization shown in enclosure (11D).) Lacking evidence to the contrary, remaining damage to the engine and all damage to the airframe occurred at or after impact with the ground.

The aircraft contacted the ground in a 50-60° nose down, left wing low attitude. This was determined by statements of Major (b) (6) (enclosure (5)) and Mr. Frazier (enclosure (4)) and by the ground imprint of the aircraft. The heading at impact was 087°M at a speed of about 300 KTS. The left wing contacted the ground first leaving a shallow imprint of the leading edge. The nose section then partially cartwheeled into the ground due to the levering action of the port wing. Following nose impact, the engine tore loose from its mounts and ripped forward through the fuselage fuel cell (shredded sections of fuel cell, engine compressor blades, and the main generator were found in the main crash depression). The engine then contacted the ground and bounced out of the crash depression. It rotated at least 1/2 turn before alighting on its tail pipe 102' from the main crash depression (enclosures (8), (11A), (11B), and (11C)). During its 102' flight it scattered compressor rotor and stator blades an additional 500' and shed most of its accessory components. Shortly after the nose of the aircraft contacted the ground the starboard wing tore loose from the fuselage and flew 114' from the main crash depression (enclosure (11A)). The forward section of the fuselage was shredded on impact and remained in the main crash depression. The rear section of the fuselage, the rudder, the horizontal stabilizer, and the tail pipe shroud were scattered on a heading of 048°M from the main crash depression (enclosure (8)).

When the aircraft first contacted the ground an explosion and fire occurred caused by an estimated 3500# of fuel remaining aboard at the time of impact. The explosion induced scattering of parts and very light fire damage was noted on the scattered debris. There was no evidence of inflight fire damage on recovered parts and statements of witnesses report lack of smoke or fire from the aircraft prior to impact.

The engine was sent to NAS Alameda O&R for priority DIR. Results of this investigation are contained in enclosure (10).

PART VII - INVESTIGATION AND ANALYSIS

As requested in COMEIGHT's msg 160143Z Aug 66, the CO NWEF assumed cognizance of the investigation and appointed the Accident Board which first viewed the accident scene five days after the mishap. A military guard at the scene established by officials at Cannon AFB on 12 Aug was interviewed by the Board. From the interview, it was ascertained that no unauthorized personnel had entered the crash area, and that no evidence had been disturbed or removed. After examination of the wreckage, the Board also concluded that rainfall occurring on three of the five intervening days did not have a deleterious effect on investigation of causal factors in the accident. A survey of the area by helicopter oriented the flight path of the stricken airplane, the distribution of wreckage and located the seat and canopy. The drop tanks were located undisturbed except for impact damage in open terrain three miles west of the crash site. The investigation is subsequently divided into three areas. Results of on-scene investigation, analysis of records and statements, and the DIR report (enclosure (10)).

On Scene Investigation

1. Heavy metallization was discovered on first stage turbine blades (enclosure (11D)).
2. Appearance of the engine and the pilot's statement gave indications of bearing failure.
3. Oil-soaked ground was found under accessory drive components, the oil tank, and mutilated fragments of oil lines located throughout the impact site in spite of intervening rain and the sandy/porous soil composition of the area.
4. There was no evidence of inflight fire. Electronic components from all areas of the airplane, particularly those in proximity to the engine and engine bays were opened and examined for melted solder joints, heat deformation and melted plastic components. None were found. Examination of the air frame skin and components showed no fire damage except that sustained following impact explosion.
5. An imprint of the turbine on the tailpipe and the appearance of the compressor indicated zero or near zero engine RPM at impact.
6. The No. 1 engine bearing located in the impact depression showed impact damage only.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

7. The main oil strainer was examined for metal and contamination. No implicating evidence.
8. The compressor casing and detached parts of it showed evidence of gouging and impact damage but no indications of compressor rub or differential expansion of the compressor casing and rotor.
9. The ejection seat was intact with separation bladders inflated.
10. The canopy was located in proximity to the seat with the canopy-seat-interlock cable attached.
11. The air conditioning turbine was found intact in the main depression. Examination showed no internal failure or foreign object ingestion.
12. The following components were examined and subsequently forwarded for analysis with the DIR:

Accessory Gear Box (All mounting pads broken off)

Flow Dividers

Fuel Control H-510917 (4 pieces, casing cracked)

Oil Pump 611157 (Smashed lines, body in pieces)

Magneto 7367 (Body smashed, shaft jammed)

Fwd Hydraulic Pump (Headplate sheared at studs)

Fuel Pump PE 8846 (Broken flange mounting, lines shredded)

Tail Pipe and Heat Shield (Complete deformation)

Fuel Flow Transmitter (Casing split, lines sheared)

13. The engine and flight instruments were so badly mutilated that no readings could be ascertained. The one exception was the RMI which indicated a heading of 078 DEG.
14. Portions of the left and right consoles were found but their mutilated condition precluded determination of switch positioning.
15. Dirt from the main impact position was screen-sifted for engine parts which were subsequently forwarded for analysis.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

Analysis of Records and Statements

1. Flight authorization, pilot qualifications and preparation for flight by the pilot and maintenance personnel were adequate and were not considered causal or contributing factors.
2. Analysis of predicted weather and that encountered were considered but eliminated as a factor. The weather encountered was not an abnormal environment.
3. The airplane was properly pre-flighted and serviced for the intended mission.
4. The airplane completed PAR 5/26/66 and was in the third calendar month of its fourth tour. The next scheduled odd-calendar inspection was due not later than 22 Sep 66.
5. There were no records indicating major maintenance or component removal or replacement since PAR completion. Records showed only routine servicing and maintenance. The airplane had flown 12.2 hrs in the previous five days with only two reported discrepancies. (See No. 9 below.) Air to Air TACAN not operating and dim advisory indicator lights.
6. The possibility of pre-oil TEE check valve failure associated with A4 AFC 325 increment V was investigated but found not applicable, the change had not been incorporated. (COMNAVAIRPAC 062119Z May 66 refers)
7. Oil consumption records and engine run down times were analyzed. Normal data - no trends apparent.
8. A review of work order and maintenance discrepancy reports did not reveal cause factors.
9. A pilot report of 10 Aug noted a max EGT of 670°C with the comment "Lots of poop." The airplane was left in an "up" status and no corrective maintenance action was taken. This overtemp condition should have initiated trouble shooting procedure for the engine indicating system and or a jet-cal. This condition was not considered a cause factor but is an important factor on engine life. The referenced "lots" of poop indicates an overtrimmed condition rather than a transient temperature condition.
10. A "time-ticked" verbatim recording of the voice communications between the ABQ ARTCC controller, the pilot of the A-4C and the pilot

SPECIAL HANDLING REQUIRED LAW PARA 66 OPNAVINST 3750.6E

8 8

of Force Jet "Livid 14" was analyzed for information not recorded in other statements or interviews. Vertical speed and determination of ejection altitude were obtained from this source. No other significant information was obtained.

11. Continuous voice communications were maintained up to the time of the engine malfunction and it was concluded that generator icing was not a factor. Partial failure due to icing can cause loss of TACAN, air conditioning, and erroneous attitude presentation. From the pilot's statement and an interview with him, these indications were not observed.
12. The "freezing" of the fuel flow indicator (pilot's statement, enclosure (2)) is unexplained, other systems operated normally on emergency generator power. Situations which could cause this condition are loss of one phase of AC input, or the severing of a phase lead. Location of the instrument is such that compressor blades from the 3rd to 5th stages would have to have severed the wire bundle following rupture of the compressor case in flight. There was no evidence to sustain this as a cause for failure.
13. The pictures taken by the F4C pilot last paragraph, enclosure (5), were reviewed. No usable information.
14. Ejection was initiated at low altitude as confirmed from the review of ABQ center recording and the statements of witnesses (enclosure (5), (6), and (7)).
15. No fire, flame or smoke was observed emitting from the stricken aircraft prior to impact (enclosure (6) and (7)).
16. External damage to aircraft prior to the crash could not be determined. Although the F4C pilot had visual contact, with the A4C, he did not reach a proximity permitting visual inspection (enclosure (5)).
17. There was no indication that the pilot accepted the airplane for flight with known discrepancies or that he initiated any in flight action that could have precipitated the accident.
18. The pilot actuated pitot heat "ON", secured auto pilot and added power in anticipation of icing conditions not because of them. Weather penetration procedure was proper.
19. There was no defined indication that the addition of power or the entry of the airplane into the precipitation area caused the subsequent engine failure.
20. The pilot stated the airplane was not re-trimmed using emergency power.

SPECIAL HANDLING REQUIRED LAW PARA 66 OPNAVINST 3750.6E

The DIR

1. The DIR analyst concluded that none of the components forwarded with the engine were contributory to the accident and that the compressor failed due to the ingestion of a foreign object, the origin of which is unknown. Frequent interviews with the analyst and possible identifications of the object and its origin were systematically analyzed and rejected. The suspected foreign object is currently being metallurgically analyzed. Pictures of the object have been given wide distribution in O&R, maintenance activities, and the airframe contractor for identification. Manuals of standard fittings were searched for correlation or identification of the object with negative results.

ANALYSIS

In analyzing the evidence from this accident, the Board considered two areas. First, what caused the engine to fail and second, what actions, if any were available or utilized by the pilot to alleviate or improve the situation.

A description of the Board's thoughts concerning the cause of the engine failure and their reasons for concurring in or denying them are stated in the following paragraphs.

When first viewed at the crash site, it was evident that the engine was stopped or turning at very slow RPM when it hit the ground. This was further confirmed by the pilot's statement wherein he reported zero RPM and zero EGT following the engine failure. The evidence indicated a main bearing failure, however in the investigation for the presence of oil, or lack of it in the engine and its components, there was strong evidence that oil was being supplied to the engine at the time of failure. Bearing failure was ruled out when the DIR Inspector found all three main engine bearings in good condition.

The Board next considered ingestion of some flammable fluid in the compressor section causing a fire or explosion in flight. This area was given extensive coverage due to the extremely heavy metalization found on the latter compressor stages and the turbine stator blades and the pilot's statement. The fuel and hydraulic lines located proximate to the engine though badly mutilated did not indicate inflight failure and no heat damage was noted on engine parts thrown clear of wreckage or in amplifiers located adjacent to the engine and tail pipe. From the statements of ground witnesses, wreckage examination, and the lack of inflight fire indications, i.e., high EGT, or fire warning to the pilot, a finding of inflight fire or explosion could not be sustained.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

8 8

The next area investigated was Foreign Object Damage. This did not at first appear likely as the aft section of the compressor and the turbine section of the engine were in excellent condition. If there was FOD, it had not progressed as far as the turbine section, before the engine stopped rotating. If FOD was causal, was the Foreign Object integral to the aircraft, the engine, or caused by some external source? The pilot reported an explosion which felt like it came from under his left foot. The only moving part located in this position is the air conditioning turbine and even if it exploded, its location is low in relation to the port inlet duct of the engine. Ingestion from this source was considered unlikely. The air conditioning turbine was found in the main crash depression, was disassembled and found to be in good working order. All other engine accessories which could have been ingested into the engine were found and examined. The main generator, because of its location ahead of the engine and its susceptibility to icing was suspect. The case and armature were found at separate spots in the main crash depression but neither showed signs of inflight failure. There was no indication to the pilot of generator icing. The Board at this time returned to the crash site to screen-sift the dirt from the crash depression in hopes of finding some other evidence. A few more first stage compressor rotor and stator blades were recovered but nothing else. By this time the DIR Inspector had gone into the engine quite thoroughly. He analyzed the metallization on the turbine and determined it was aluminum from the 4th through 7th stage compressor rotor blades. He was also certain that FOD had caused the engine failure due to the appearance of the front stage compressor blades, but he was uncertain as to the source or type of FOD. In sifting out the dirt from the compressor section he found the foreign object shown in enclosure (11E, F, & G). His analysis was that the item was so peened that the damage to it could only have occurred inflight as a result of being ingested into the engine during hi-speed rotation. The origin of this item is still unresolved. It is peculiar in that its outer case is steel, it contains a threaded aluminum insert, and at one end a piece of brazed tubing was probably attached. A metallurgical examination is in process and a supplemental report will be submitted if the object is identified. The DIR Inspector stated that it is not integral to the engine and so far the Board, with Douglas Aircraft Company assistance, has been unable to determine its location on the A4 airframe. Remaining possibilities considered were that it was a piece of ground handling equipment or a special tool which was left in the intake duct and remained undetected during maintenance and preflight; that the object was drawn into the intake duct during taxi or takeoff; or that it was a piece of FOD which somehow was caught in the refueling store drogue basket during a ground maintenance period and was dislodged at the time the pilot commenced inflight refueling. If any of this theorizing is plausible, the item had to remain lodged against the inlet guide vanes for some indefinite time before it came loose and fell back into the

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

compressor face. The possibility exists that it became unbalanced when ice formed on it after the aircraft entered the precipitation area, or that the piece of brazed tubing which could have been attached to it was finally worn off by vibration or abrasion. The Board theorized that the hi-pitched squeal the pilot heard could have been the tubing being ground off initially until finally the entire steel section was pulled into the compressor section striking the first stage rotor blade as depicted in enclosure (11F). At this time several first stage blades failed and progressed into the third through seventh stages which vaporized due to hi rotational speed and the engine flamed out during the rapid deceleration. Compressor failure due to rotor shifing is a possibility that could not be determined. This type failure could have been induced without a bearing failure indication. Lacking evidence to the contrary, the Board felt that the illusion of an explosion under the cockpit was caused by induced vibratory airframe stress rather than a failure in this area. The yaw could have been the result of the loss of stability augmentation following power failure, or a shift in lateral location of the engine because of failure of the forward engine mount coincident with compressor failure.

As to the pilot's actions during the flight, the Board concluded the following: The flight was duly authorized and the pilot was executing the flight plan in an approved manner. There were no indications that pilot actions prior to the engine failure induced it or that he could have known of the impending failure from cockpit indications. He was operating within the allowable engine operating range at 96% RPM and 610° EGT. He was aware of the effects of icing on the engine and was correct in his procedure in anticipating them. After the explosion, flameout, and engine failure, the pilot used proper emergency procedures commensurate with the situation. His decision to glide toward Cannon AFB was proper in that he initially anticipated a relight prior to landing. He could normally expect a glide range of 50 miles from 27,500' with a clean airplane and a windmilling engine. In this case he had three drop tanks, a frozen engine, and the RAT extended, which cut his glide range to about 30 miles. He attempted a relight at 20,000' which was unsuccessful. At this time the pilot states he knew he was going to have to eject.

The only question the Board has as to any pilot action during this flight is whether the pilot waited too long to eject. After the crash the pilot informed the flight surgeon that he believed he ejected at 8000' MSL or about 4000' AGL. The Board determined that the pilot ejected at 5400' MSL or about 1200' AGL. This is based on voice tapes reviewed at Albuquerque Air Route Traffic Control Center. The last statement made by the pilot concerning his altitude was as he passed through 7000'. Thirty-eight seconds later the accompanying F4C pilot

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

8 8

stated "He is ejecting right now." Based on the aircraft's rate of descent (averaged rate from 20,000' to 7000'), the pilot ejected at 5400' MSL. The elevation of the terrain at the crash site is 4200'. This is well within the RAPEC ejection envelope and the pilot may have waited to insure that his aircraft would not strike a populated area, however had his ejection seat not worked there would not have been sufficient time or altitude to attempt manual egress from the aircraft. The Board assumed that the pilot was aware of the terrain elevation and that his decision to delay ejection was predicated on aircraft clearance from populated areas.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

PART VIII - CONCLUSIONS AND RECOMMENDATIONS

1. It is concluded that:

- a. The engine failed due to foreign object ingestion.
- b. There was no pilot action that contributed to the failure, nor any inflight pilot procedure that could have prevented the accident.
- c. That ejection was initiated at an altitude which left little margin for alternate emergency action even though the requirement for ejection was confirmed prior to passing an altitude of 10,000'.
- d. There was no evidence to sustain maintenance, personnel or supervisory error in the accident though the possibility exists that a foreign object was inadvertently left in the intake duct.

2. It is recommended that:

- a. Pilots be acute in maintaining engine operation within defined operating limitations and that they bring obvious exceptions to the attention of maintenance personnel for corrective action.
- b. Pilots be continually aware of the relationship existing between local ground elevation and airplane altitude to assure adequate terrain clearance should emergency egress be required.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

ENCLOSURES

1. Medical Officer's Report and Appendix One (original only)
2. Statement of Pilot: CDR J. H. Alvis, USN
3. Maintenance Control Officer's Statement, (b) (6) USN
4. Ejection Seat History
5. Statement of MAJ (b) (6) USAF, pilot of F4C "Livid 14"
6. Statement of Mr. Melvin Estes (witness)
7. Statement of Mr. Earl Prazier (witness)
8. Wreckage Diagram
9. Map of Crash Scene
10. DIR Report, J65-W16A Ser 612332
11. Photographs (7)
12. Photostat of DD-175
13. Statement of Fire Chief Cannon AFB (original only)
14. Helicopter Rescue Report (original only)

DEPARTMENT OF THE AIR FORCE

832D TACTICAL HOSPITAL (TAC)

CANNON AIR FORCE BASE, NEW MEXICO 88101



REPLY TO
ATTN OF

SG-AM

17 Aug 66

SUBJECT:

Statement

TO:

When it may Concern

1. Commander John H. Alvis walked into the Air Force Clinic on the evening of 12 Aug 66 at 1925 hours stating that he had just ejected from his aircraft near Melrose, New Mexico.

2. He walked in completely unassisted and his only complaint was (b) (6). Physical examination revealed no signs of injury anywhere. Even the right ankle was not swollen or tender. No x-rays were taken.

3. (b) (6) and the patient sent on his way with instructions to check in with his own dispensary if he had any persistent symptoms (b) (6) or any other area.

(b) (6)

(b) (6)

CAPT, MC, USAF

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 66 OF OPNAVINST 3750.6E

ENCLOSURE (1) APPENDIX I

Statement of Pilot, CDR J. H. ALVIS, concerning A4C 148567 accident on 12 August 1966

At 1544 on 12 Aug 66 I departed NAS Lemoore on an IFR flight to Dyess AFB, Abilene, Texas. The flight proceeded normally until passing Albuquerque. I was cruising at FL 330 in VFR flight conditions. There were numerous cumulus cloud buildups in the area and some stratus clouds. Albuquerque Center called and said there was a precipitation area about 20 miles long and 5 miles wide ahead of me and asked if I wanted a vector to the south. I looked the area over and could see nothing but stratus clouds ahead and to the left of my course whereas there were some cumulus to the south. I informed center of this fact and held my course. I entered the clouds and encountered light precipitation and light turbulence. Albuquerque informed me that they had me entering the precipitation area. Light ice began to form on the windscreen. I called Albuquerque Center and asked them again the width of the precipitation area. The controller stated that it was about 20 miles long and 5 miles wide oriented east and west. By this time I thought I should be almost through it and held my course. The conditions were right for ice to form on the inlet guide vanes so I watched the RPM and EGT carefully. The RPM was steady at 94% and the EGT was steady at about 580°. This was giving me an IAS of 250 knots and a MACH of 0.71. A Marine F4 reported moderate to severe turbulence at FL 330 in this area. I disengaged the autopilot in anticipation of turbulence but still encountered only light turbulence. At this time I began to hear a very faint high pitched squeal. I quickly checked the engine instruments and they were steady. I don't remember the specific oil pressure reading, but it had been reading 34 psi and must have been still in the 12 o'clock position or I would have noted it. I did not associate the squeal with the engine as there was no vibration and the engine still sounded normal. The squeal rapidly (maybe 30 seconds) built up to a crescendo and there was a moderate explosion in what seemed to be the port side of the nose section of the aircraft with the A/C yawing a few times. All electrical power was lost and the radio went dead. I dropped the emergency generator and concentrated on the flight instruments to ensure that I maintained control of the aircraft. The A/C rolled inverted twice but ejected rapidly each time. The standby gyro operated normally. It was apparent by this time that I had flamed out and the aircraft was descending. I checked the engine instruments; the RPM, EGT and oil pressure were zero. I did not note the cabin pressure nor do I remember a rapid drop in cabin pressure. The fuel flow read 1500 pounds per hour. I moved the throttle back and forth, but there was no thrust change nor any change in the fuel flow. I moved the throttle to the off position and informed Albuquerque Center I had flamed out and asked for a steer to the nearest field. They gave me a steer of 090°/45 miles for Cannon AFB. I made a slight turn to the right to 090° and set up a glide at about 210 knots. I was convinced that the explosion had not been in the engine so I got out my pocket check list and reviewed the relight procedures in anticipation of a relight attempt at 20,000 feet. The RPM, EGT and oil pressure were zero. The fuel quantity read 3500 pounds and the fuel flow still read 1500 pounds per hour. At about 25,000 feet I broke into the clear, visibility was unlimited. I could see one small town which I later learned was Melrose, New Mexico. Albuquerque Center continued to give me steers to Cannon AFB. At 20,000 I tried a relight but with the RPM at zero and no change in fuel flow, I did not expect a relight. I watched the EGT and fire warning Light


SPECIAL HANDLING REQUIRED IN ACCORDANCE PARA 66 OPNAVINST 3750.6E

ENCLOSURE (2)

but neither gave any response. After about 45 seconds I moved the throttle to off. I was convinced then that I would have to eject. I tried one more air start but again there was no response. An Air Force RF4C was joining on me so I told him to stay clear while I dropped my tanks. I wanted to get as near Cannon as possible. I selected ALL, pulled the emergency release and the two empty tanks and blivette dropped. I looked below and saw nothing but open fields so I informed Albuquerque Center that I was going to eject. The aircraft was trimmed nose down. I left it that way as I wanted it to go down in the open fields after I ejected.

The ejection, seat separation and parachute opening were normal. The ejection, wind blast and parachute opening shock were less severe than I had anticipated. I removed my oxygen mask and decided not to release one side of the seat pack as for water landings. I looked the countryside over and tried to turn to face down wind but could only get about 90° to my line of drift. I hit the ground quite hard and was dragged about 20 feet while releasing the Koch fittings. No difficulty was experienced in releasing the fittings. Within a few minutes a farmer drove up and took me about a mile over to where the aircraft had hit. Within about 30 minutes an Air Force helicopter arrived and took me to Cannon AFB.

I do not know the cause of this accident, but I am quite sure that the air conditioning turbine exploded and by some means caused the engine to seize. The only thing unusual at the time of the explosion was the ice forming on the windscreen. I have seen this a number of times and on two occasions I have had the main generator ice up which required dropping the emergency generator. Several times while flying in visible moisture above the freezing level I have had ice cover the ram air ports on the inlet guide vane causing the engine RPM to decrease, but a descent to below freezing level has always cleared up the ice.


J. H. ALVIS
CDR, USN

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 66 OF OPNAVINST 3750.6E

18 August 1966

Subj: Maintenance Control Officers Statement

Aircraft BUNO 148567

Ref: VA-112 AAR 3-66A

1. Aircraft was fueled to 5400 lbs internal and 4000lbs external.
Aircraft refueled in flight from A4C tanker.
2. Aircraft was serviced with 4 1/2 quarts of oil.
3. Aircraft was preflighted IAW A4C MRC requirements and is considered to have been properly prepared for flight.

(b) (6)

LT

USN

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OPNAVINST 3750.6E

ENCLOSURE (3)

EJECTION SEAT HISTORY

1. From the airplane log books. The following data was extracted by the Board.

RAFZO SER. NO. A18-1098
INSTALLED A4C BUNO 148567 9-12-61 COMP. PAR. 5-20-66 BY NAS ALAMEDA

THE FOLLOWING TECHNICAL DIRECTIVES INC.

INTERIM AIRCREW SYSTEMS BULLETINS

12A	INC	NAS ALA.	5-12-66
64	INC	NAS ALA.	5-18-66
78	INC	NAS ALA.	4-14-66

AIRCREW SYSTEM BULLETINS

57	INC	VA-112	3-17-65
59	INC	VA-112	3-17-65
69	INC	VA-112	9-3-65
12 AMD 2	INC	VA-22	8-26-63
15	INC	VA-22	9-16-63

AIRCREW SYSTEM CHANGES

31	INC	VA-112	4-12-65
41	INC	VA-112	1-21-66
1	INC	NAS ALA.	5-12-66
57	INC	NAS ALA.	5-12-66
INT. 37	INC	NAS ALA.	5-12-66

A4 INT. A/P CHANGES

270	INC	VA-22	7-27-64
-----	-----	-------	---------

A/C CLOTHING AND SURVIVAL EQUIPMENT BULL.

15-62	INC	VA-22	8-7-62
-------	-----	-------	--------

CNAF A4 A/C BULL.

3-61	INC	VA-22	11-24-61
9-61	INC	VA-22	11-24-61
49-62	INC	VA-22	7-26-62
57-62	INC	VA-22	9-7-62
57-62	INC	NAS ALA.	2-19-63
74-62	INC	VA-22	11-5-63

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

Enclosure (4)

MISCELLANEOUS HISTORY OF SPECIAL VALUE

6-30-66 CNAP 070611Z MAY 66. THE AGE LIFE OF RAPEC MK 1 MOD 1 IS EXTENDED TO 60 MONTHS FROM DATE OF MANUFACTURE PROVIDED OPERATING TEMPERATURE RANGE IS RESTRICTED TO RANGE FROM MINUS 10° TO PLUS 165°F. UNITS WITH CURRENT AGE LIFE OF 48 MONTHS OR LESS ARE QUALIFIED FOR USE AT MINUS 10° TO PLUS 165°F UNTIL 48 MONTHS OLD AND THEN REVERT TO TEMPERATURE RANGE INDICATED ABOVE. (NOTE) MK 1 MOD 1 INSTALLED 5-78-66 NAS ALA. EXPIRATION DATE 7-67.

2. The Board concluded that there were no factors in the RAPEC history that had an adverse effect on proper functioning of the seat.

SPECIAL HANDLING REQUIRED IAW PARA 66 OPNAVINST 3750.6E

Statement of Major (b) (6) FR (b) (6) USAF, Concerning A4C 148567
Accident on 12 August 1966.

Enroute from George AFB to Cannon AFB in an RF4C we heard an aircraft call ARTC saying he had flamed out and needed a steer to the nearest airfield. He was given a vector to Cannon AFB and ARTC began keeping us above the disabled aircraft's altitude as he descended. It became obvious after a few minutes that he wouldn't get an airstart and I offered to fly his wing on the descent to give any assistance possible. He accepted and ARTC vectored me toward his position, some seven or eight miles to the west. By this time the disabled aircraft was passing through eleven thousand feet.

By the time I slowed my aircraft to forming speed, the disabled ship's pilot had dropped his external tanks and was passing through approximately 7000 feet MSL. I was unable to get close enough to the aircraft to look it over carefully since at about this time the pilot had made the decision to eject.

The aircraft nosed over sharply, the ejection seat fired and the personnel parachute deployed. The aircraft continued a 50-60 degree dive, rolled to the left and maintained that attitude until striking the ground. It exploded on contact. I circled the pilot as he descended and after he landed in a field, I determined that he was OK and so notified Cannon approach control.

I made a pass over the crash scene, located about 1 1/4 miles from the pilot in an open field, took pictures as I passed over it and departed for Cannon to land.

/s/ (b) (6)
Major, USAF

Total flying time: 3100 hours
Total rated time: 14 years
Senior pilot.

CERTIFIED TO BE A TRUE COPY OF HIS STATEMENT

(b) (6)
CDR, USN

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 66 OF OPNAVINST 3750.6E

ENCLOSURE (5)

Statement of Mr. Melvin ESTES, International Harvester Dealer, Melrose,
New Mexico, Concerning A4C 148567 Accident on 12 August 1966

On the afternoon of the airplane crash, I was driving in my pickup truck 6 miles north and 5 miles west of Melrose, New Mexico, when I observed two aircraft at low altitude heading north east. Looking behind the aircraft, I saw 3 objects falling down from them. The two aircraft slowly turned right to an approximate heading of south east. One aircraft appeared to be in trouble, and the other aircraft stayed higher. The aircraft in trouble got lower and lower. Almost simultaneously I saw the flash of the aircraft hitting the ground and exploding and the pilot descending in a parachute. At no time before the crash did I see any smoke or fire coming out of the stricken aircraft.

/s/ MELVIN ESTES

Mr. Estes is considered to be a reliable witness.

CERTIFIED TO BE A TRUE COPY OF HIS STATEMENT.

(b) (5)

CDR, USN

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 66 OF OPNAVINST 3750.6E

ENCLOSURE (6)

Statement of Mr. Earl FRAZIER, Employee of International Harvester Dealer,
Maltrose, New Mexico, Concerning A4C 148567 Accident on 12 August 1966.

On Friday afternoon on 12 August, I was working on my pickup truck in the driveway by my house when I observed a low flying aircraft heading east. At this time, it was about 1/2 mile north of my house. It appeared to be in trouble, because it was going so slow and the wings were rocking slowly side ways. Another aircraft flew along side of it and then added power and pulled up higher. Shortly after this, the low flying aircraft nosed over steeply and the pilot came flying out. His parachute opened, and he floated to the ground. Meanwhile, the aircraft dived straight into the ground and exploded. Before the crash, I did not notice any smoke or fire coming from the aircraft.

/s/ EARL FRAZIER

Mr. Frazier is considered to be a reliable witness.


CERTIFIED TO BE A TRUE COPY OF HIS STATEMENT.

(b) (6)

CDR, USN


SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 66 OF OPNAVINST 3750.6E

ENCLOSURE (7)



A-4C 148567 Wreckage Diagram,
oriented from center of crash
depression (all headings magnetic)

Special Handling Required in accordance with Paragraph 66 of OPNAVINST 3750.6E



CURRY COUNTY SECTIONAL MAP
showing location of crash
site and position of witnesses,
(each square is 1 mile on a side)

0
UNCLAS
FM NAS ALA EDA
TO RUMSAA/AMTIRSYTON REPAC
INFO RUEC/NAVAVIRSYBON
RUECDS/NAVAVIRSYBON
RUMSAA/ITEF KIRTLAND AFB
RUMSAA/ATKRON ONE ONE TWO
RUMSAA/COMNAVIRPAC
RUMSAA/CARAIR ONE ELEVEN
ZEN/COMFAIRALL EDA
RUEGUC/OCASO FODDRIDGE
RUEGFA/NATSF PHILA
RUEGPA/NAS QUONPT
BT
UNCLAS

FAILURE ANALYSIS J65-116A ENGINE SERIAL 612332 FROM A-4C AIRCRAFT
BUNO 140567

A. YOUR 283045Z AUG NOTAL

B. ATKRON ONE ONE TWO AAR SER 3-66A

1. ENGINE RECEIVED IN MUTILATED CONDITION. SEVENTEEN FIRST STAGE

PAGE TWO RUMSAA 014 UNCLAS

COMPRESSOR ROTOR BLADES RECOVERED, TWENTY MISSING. ALL SECOND AND
THIRD STAGE COMPRESSOR ROTOR BLADES RECOVERED. ALL FOURTH THROUGH
SEVENTH STAGE COMPRESSOR ROTOR ALUMINUM BLADES WIPE OUT. EIGHTH
THROUGH THIRTEENTH ROTOR BLADES INTACT EXCEPT FOR ROTATIONAL DAMAGE.
ELEVEN COMPRESSOR ENTRANCE GUIDE VANES RECOVERED. ALL HAD ROTATIONAL
DAMAGE AT TRAILING EDGE. FIFTEEN FIRST STAGE COMPRESSOR STATOR
BLADES RECOVERED. MOST OF REMAINING STAGES OF STATOR BLADES WERE
RECOVERED. ALL COMPRESSOR BLADES HAD IN-FLIGHT ROTATIONAL DAMAGE.
ENGINE CONDITION INDICATED LITTLE OR ZERO RPM AT TIME OF IMPACT.
2. SCREENING OF DEBRIS FROM COMPRESSOR SECTION REVEALED A FOREIGN
OBJECT RESEMBLING A B-NUT TUBING CONNECTOR. DIMENSIONS OF OBJECT,
ONE-HALF INCH LONG, THREE-QUARTERS INCH DIAMETER, HAVING THREE-
SIXTEENTH INCH HOLE IN CENTER, AND ONE-SIXTEENTH INCH WIDE BY ONE-
SIXTEENTH INCH DEEP GROOVE AROUND CIRCUMFERENCE. OUTER SHELL OF
OBJECT IS STEEL AND IS SEVERELY NICKED AND POUNDED. THIS CONDITION
COULD ONLY HAVE BEEN INDUCED BY CONTINUALLY POUNDING AND NOT FROM
IMPACT AT TIME OF CRASH. ONE FIRST STAGE COMPRESSOR ROTOR BLADE HAD
A GOUGE ON LEADING EDGE PATTERNED SIMILAR TO FOREIGN OBJECT.
SECTIONING OF STEEL OBJECT REVEALED A ONE-HALF INCH OUTSIDE DIAMETER
ALUMINUM FERRULE WITH SIZE TWENTY-EIGHT THREAD. A STEEL WASHER

SPECIAL HANDLING
REQUIRED IN ACCORD
PARA 66 OFNAV
INST 3750.6E

PAGE THREE RUMSAA 014 UNCLAS

WHICH APPEARED TO BE ATTACHED TO END OF TUBING. FERRULE SCREWED
INTO STEEL OUTER CASE SECURING WASHER AND TUBING TO STEEL OUTER
CASE. UNABLE TO IDENTIFY FOREIGN AND ITS SOURCE. OBJECT IS NOT
ENGINE PART.


3. TURBINE ROTOR AND STATOR BLADES WERE HEAVILY COATED WITH
ALUMINUM METALIZATION CAUSED FROM WIPEOUT OF ALUMINUM COMPRESSOR
BLADES IN FLIGHT. **WA FOREIGN OBJECT**

4. FRONT, CENTER, AND REAR MAIN ENGINE BEARINGS WERE SATISFACTORY
EXCEPT FOR IMPACT DAMAGE.

5. CONCLUDE ENGINE FAILURE WAS CAUSED BY PRECEDING DESCRIBED FOREIGN
OBJECT PENETRATING THROUGH ENGINE COMPRESSOR INLET CAUSING IN-
FLIGHT COMPRESSOR FAILURE. SHOULD IDENTIFICATION OF FOREIGN OBJECT
BE MADE AT A LATER DATE. A SUPPLEMENT TO THIS REPORT WILL BE

INITIATED.

ENCLOSURE (10)




VA 112 AAR 3-66A

VIEW OF CRASH SITE SHOWING: ① CENTER OF CRASH DEPRESSION ② STBD WING ③ 165 ENGINE. SEE ENCLOSURE (8) FOR HEADING AND DISTANCE INFORMATION.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST 3750.61

ENCLOSURE (11A)



VA 112 AAR 3-66A
FRONT VIEW OF COMPRESSOR SECTION OF J65 ENGINE SER 612332 AT CRASH SITE. SEE ENCLOSURE (8) FOR LOCATION
FROM CENTER OF CRASH DEPRESSION.
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST 3750.6E

ENCLOSURE (11B)




VA 112 AAR 3-66A

REAR VIEW OF TAIL PIPE OF J65 ENGINE SER 612332 AT CRASH SITE. SEE ENCLOSURE (8) FOR LOCATION FROM CENTER OF CRASH DEPRESSION.



SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST 3750.6E

ENCLOSURE (11C)



VA-112 AAR 3-66A
VIEW OF HEAVY METALIZATION ON FIRST STAGE TURBINE STATOR BLADES OF
J65 ENGINE SER 612332.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST
3750.6E.



VA-112 AAR 3-66A

VIEW OF J65 ENGINE ENTRANCE GUIDE VANE & 1ST STAGE COMPRESSOR
BLADE SHOWING POSSIBLE INITIAL IMPACT POINT OF FOREIGN OBJECT.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST
3750.6E ENCLOSURE (11E)



VA-112 AAR 3-66A

VIEW OF FOREIGN OBJECT SHOWING EXCESSIVE PEENING CAUSED BY
ROTATIONAL DAMAGE.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST
3750.6E
ENCLOSURE (11F)

STEEL CASING

BRAZED TUBING

WASHER

ALUMINUM INSERT

1/16" X 1/16" SLOT

VA-112 AAR 3-66A

SECTIONED VIEW OF FOREIGN
OBJECT SHOWING STEEL CASING &
THREADED ALUMINUM INSERT.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST
1750.6E

ENCLOSURE (11G)

MILITARY FLIGHT PLAN		VA-112 / NAS Lemoore, CA		14 JUL 66	
TYPE OF FLIGHT PLAN <input checked="" type="checkbox"/> DAY <input type="checkbox"/> NIGHT		RADIO CALL TO CODE NH 203	AIRCRAFT REGISTRATION A4/B	ESTIMATED TIME AIRPORT -420	DEPARTURE TIME 220
INITIAL CRUISING ALTITUDE 320	POINT OF DEPARTURE NAS Lemoore	STANDARD INSTRUMENT DEPARTURE NAME AND NUMBER Lemoore #2 Pilot Tran		TO Bakersfield	
IFR	VFR	ROUTE OF FLIGHT			
✓		J-65 PND, J-6 ABQ, J-72 TIO, B A81 Dyes AFB 02145 VFR			
REMARKS ① TACAN ONLY ② VH 204 WILL CANCEL IFR & Return to VRC after refuel between RFL and PND when reaching FL 320. MARSAT					
NAME/HONOR CODE	PSGR/CARGO CODE				
HOURS FUEL ON BOARD 0.3+30	DIST TO DESTN 1100	ALTERNATE AIR FIELD NR		ETE TO ALTN	REQUEST CLEARANCE AFTER
INST RATING Special	SIGNATURE OF PILOT IN COMMAND <i>[Signature]</i>		SIGNATURE OF APPROVING AUTHORITY (b) (6)		DATE 8/12/66
CREW/PASSENGER LIST					
DUTY	NAME AND INITIALS	GRADE	SERVICE NO.	ORGANIZATION AND LOCATION	
PILOT IN COMMAND	ALVIS, JH	CDR	(b) (6)	VA-112 / NAS Lemoore	
P	(b) (6)	LTJG	(b) (6)	" "	
Bu NO 147714 NH 204					
Standard					
PILOTS PREFLIGHT CHECKLIST					
✓	NOTAMS	✓	AIRSPACE RESTRICTIONS	✓	AIRCRAFT/DESTINATION NAV AIDS
✓	WEATHER AND WINDS	✓	CHARTS, PUBLICATIONS, MAPS	✓	DD FORM 365F (Weight and Balance Clearance Form F)

DD FORM 175


PREVIOUS EDITIONS OF THIS FORM ARE OBSOLETE.

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OF OPNAVINST 3750.6E
ENCLOSURE (12)

Statement of Mr. C. T. SKEEN, Cannon AFB Fire Chief, Concerning

AIRCRAFT ACCIDENT - 12 AUGUST 1966
NAVY A-4D SERIAL NO. 203

At 1758 hours, 12 August 1966 the fire department alarm room operator was notified by Cannon Tower over primary crash circuit that a Navy A-4D had crashed. Cannon Tower stated pilot had ejected and was in a field probably west of the crash site. The location of the crash site was given as G-4 on the Cannon AFB Grid map, which placed the crash in the vicinity of Melrose, New Mexico. The Assistant Chief's P/U and the O-11A crash truck responded immediately and arrived at the crash site shortly after the H-43B helicopter had evacuated the pilot. It was observed that one small fire was burning in the crater. The Melrose Municipal Fire Department put out the grass fire surrounding the point of impact. The A/C had made contact with the ground in grassland near an abandoned farm house approximately 4 miles north and 2 west of Melrose, New Mexico. The aircraft disintegrated on impact, and aircraft wreckage was scattered over an area approximately 900 feet long and 300 feet wide. The burned grass area was approximately 30 feet wide and 45 feet long.


CLIFFORD D. SKEEN
Base Fire Chief

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARAGRAPH 66 OF OPNAVINST 3750.6E

ENCLOSURE (13)

DAL325

006210

PP RUUSAL

DE RUWJDAAG524 2250345

ZNR UUUUU

P 122030Z

FM DET 2 WARRC CANNON AFB NMEX

TO HQ ARRS ORLANDO AFB FLA

INFO RUWJDAAG/HQ WARRC HAMILTON AFB

RUWJDAAG/HQ 33D COMBAT SUPPORT GP CANNON AFB NMEX

RUCIEUA/HQ MAC SCOTT AFB ILL

RUECM/HQ USN WASHINGTON DC

RUUSAL/CHDR NAS LENOORA CALIF

RUEDHQA/HQ USAF WASHINGTON

BT

UNCLAS DET 2 WARRC 00197 12 AUG 66.D

FOR ARRS ARSCP, USAF AFXOPH, MAC MACCOAT AND MCP

1. RCS: 1-ARS-F1, OPENING/CLOSING REPORT

2. DET 2 WARRC 2-12 AUG 66/D

3. RECOVERED ONE PILOT EJECTED FROM USN A-4C

4. CANNON AFB BASE OPERATION 12 AUG 66 (Alerting Agency & date notified)

5. ONE HH-43B AT 1825 LOCAL (Type and time of initial SAR action)

6. 34-28N/104-18W (Location of incident)

7. VFR (Weather at time of incident)

8. CANNON AFB COMMAND POST (Controlling agency)

PAGE

PAGE 2 RUWJDAAG524 UNCLAS

9. CANNON AFB APPROACH CONTROL (Agency locating objective)

10. DET 2 WARRC HH-43B (Agency and method used to rescue survivors)

11. ONE SURVIVOR (Number of survivors)

12. ONE (Number of persons saved)

13. RETURNED TO CANNON AFB (Disposition of survivors)

14. ONE/30 MIN HH-43B CANNON AFB (Sorties/flying hrs by type aircraft)

15. FIVE VEHICLES/TEN GROUND PERSONNEL (No of vehicles/ground personnel used)

16. NONE (Additional information)

BT

ACT AO.....DATE/TIME.....Z

ODO.....DATE/TIME.....Z 15/0636Z

A/AA AD CM CR AT ASO

NNNN

(COPIES VA-112) 13/0636Z

AUGUST 13 1966 RL

PRIORITY/122030Z:

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH PARA 66 OPNAVINST 3750.6E

ENCLOSURE (14)

NNNNZCZCNASC245DCB 66802E047

RR RUCKDG

DE RUWSAA 014 2522336

ZNR UUUUU

R 091948Z SEP 66

FM NAS ALAMEDA

TO RUWDAF/NAVAIRSYS COMREPAC

INFO RUECH/NAVAIRSYS COM

RUCKDG/NAVAVNSAFECEN NORVA

RUWJFNA/HWEF CIRTLAND AFB

RUWSAL/ATKRON ONE ONE TWO

RUWDAF/COMNAVAIRPAC

RUWDAF/CARAIRWING ELEVEN

ZEN/COMFAIRALAMEDA

RUEGUC/DCASO WOODRIDGE

RUEGFA/NATSF PHILA

RUEGPA/NAS QUONPT

BT

UNCLAS

FAILURE ANALYSIS J65-W16A ENGINE SERIAL 612332 FROM A--4CAIRCRAFT
BUNO 4148567

A. YOUR 200045Z AUG NOTAL

B. ATKRON ONE ONE TWO AAR SEA 3-66A

1. ENGINE RECEIVED IN MUTILATED CONDITION. SEVENTEEN FIRST STAGE

PAGE TWO RUWSAA 014 UNCLAS

COMPRESSOR ROTOR BLADES RECOVERED, TWENTY MISSING. ALL SECOND AND THIRD STAGE COMPRESSOR ROTOR BLADES RECOVERED. ALL FOURTH THROUGH SEVENTH STAGE COMPRESSOR ROTOR ALUMINUM BLADES WIPED OUT. EIGHTH THROUGH THIRTEENTH ROTOR BLADES INTACT EXCEPT FOR ROTATIONAL DAMAGE. ELEVEN COMPRESSOR ENTRANCE GUIDE VANES RECOVERED. ALL HAD ROTATIONAL DAMAGE AT TRAILING EDGE. FIFTEEN FIRST STAGE COMPRESSOR STATOR BLADES RECOVERED. MOST OF REMAINING STAGES OF STATOR BLADES WERE RECOVERED. ALL COMPRESSOR BLADES HAD IN-FLIGHT ROTATIONAL DAMAGE. ENGINE CONDITION INDICATED LITTLE OR ZERO RPM AT TIME OF IMPACT.

2. SCREENING OF DEBRIS FROM COMPRESSOR SECTION REVEALED A FOREIGN OBJECT RESEMBLING A B-NUT TUBING CONNECTOR. DIMENSION OF OBJECT, ONE-HALF INCH LONG, THREE-QUARTERS INCH DIAMETER, HAVING THREE-SIXTEENTH INCH HOLE IN CENTER, AND ONE-SIXTEENTH INCH WIDE BY ONE-SIXTEENTH INCH DEEP GROOVE AROUND CIRCUMFERENCE. OUTER SHELL OF OBJECT IS STEEL AND IS SEVERELY NICKED AND POUNDED. THIS CONDITION COULD ONLY HAVE BEEN INDUCED BY CONTINUALLY POUNDING AND NOT FROM IMPACT AT TIME OF CRASH. ONE FIRST STAGE COMPRESSOR ROTOR BLADE HAD A GOUGE ON LEADING EDGE PATTERNED SIMILAR TO FOREIGN OBJECT. SECTIONING OF STEEL OBJECT REVEALED A ONE-HALF INCH OUTSIDE DIAMETER ALUMINUM FERRULE WITH SIZE TWENTY-

EIGHT THREAD. A STEEL WASHER

PAGE THREE RUWSAA 014 UNCLAS

WHICH APPEARED TO BE ATTACHED TO END OF TUBING. FERRULE SCREWED INTO STEEL OUTER CASE SECURING WASHER AND TUBING TO STEEL OUTER CASE. UNABLE TO IDENTIFY FOREIGN AND ITS SOURCE. OBJECT IS NOT ENGINE PART.

OBJECT

3. TURBINE ROTOR AND STATOR BLADES WERE HEAVILY COATED WITH ALUMINUM METALIZATION CAUSED FROM WIPED OUT OF ALUMINUM COMPRESSOR BLADES IN FLIGHT.

4. FRONT, CENTER, AND REAR MAIN ENGINE BEARINGS WERE SATISFACTORY EXCEPT FOR IMPACT DAMAGE.

5. CONCLUDE ENGINE FAILURE WAS CAUSED BY PRECEDING DESCRIBED FOREIGN OBJECT PENETRATING THROUGH ENGINE COMPRESSOR INLET CAUSING IN-FLIGHT COMPRESSOR FAILURE. SHOULD IDENTIFICATION OF FOREIGN OBJECT BE MADE AT A LATER DATE, A SUPPLEMENT TO THIS REPORT WILL BE INITIATED.

THIS COMPLETES ACTION ON YOUR CONTROL 3847-67.

BT

A4C 148567

JA-112 3-6C

8-12-66

SEP 1966

NNNNOAC204DGA796VBA833

RR RUCKDG

DE RUWJFNA2034 241211Z

ZNR UUUUU

R 292041Z AUG 66

FM CO USNWEF KIRTLAND AFB NMEX

TO RUWSAL/CO ATKRON ONE ONE TWO NAS LEMOORE CALIF

INFO RUCKDG/CMDR US NAVAL AVIATION SAFETY CENTER NAS NORFOLK VA

RUWDAK/COMDR ATTACK CARRIER AIR WING ONE ONE NAS MIRAMAR CALIF

BT

UNCLAS

VA 112 AAR 3-66A (OFFICIAL USE ONLY)

1. DIR OF POWER PLANT IN SUBJ ACCIDENT CONTINUING. SEVEN
WORKING DAY EXTENSION REQUESTED. TIME EXTENSION CONSIDERED
JUSTIFIABLE IN DETERMINING CAUSATIVE FACTORS OF ENGINE
FAILURE. REQUEST REPLY ONLY IF NEGATIVE.

BT

#204/66

Cog: R/S
AT

A4C 148567

VA 112 3-66

8-12-66

ang.
292041Z

NNNNZCZC408DGB580CBH323

RR RUCKDG

DE RUWDAF 45B 2320045

ZNR UUUUU

R 200045Z AUG 66

FM NAVAIRSYSCOMREPAC

TO RUWJFNA/NWEF KIRTLAND AFB

RUWSAA/NAS ALAMEDA

INFO RUCKDG/NAVAVNSAFECEN

RUWSAL/ATKRON ONE ONE TWO

ZENI/COMNAVAIRPAC

RUWJAA/EIGHT THREE TWO D ADIV, CANNON AFB

RUWDAK/COMCARAIRWING ELEVEN

RUWSAA/COMFAIRALAMEDA

BT

UNCLAS

J65 S/N 612332 ENGINE AND SUSPECT FAILED COMPONENTS

A. FONECON LCDR PORTER/FRR-335 ON 19 AUG 66

B. 832D ADIV CANNON AFB N MEX 181440Z

C. COMNAVAIRPAC/BWFRRPAC INST 4730.8A

1. NWEF KIRTLAND: REF A ADVISED REF B ENGINE AND SUSPECTED FAILED COMPONENTS OF VA-112 AAR SER 3-66A BEING FORWARDED YOUR ACTIVITY FFT NAS ALAMEDA APPROX 22 AUG. REQ MARK FOR PRIORITY DIR IAW REF C. ADYHIPDA, REFER NAVAIRSYSCOMREPAC CONTROL NR 3037-67.

PAGE TWO RUWDAF 45B UNCLAS

2. NAS ALAMEDA: REQ CONDUCT FAILURE ANALYSIS SUBJ ENGINE AND SUSPECT COMPONENTS IAW REF C. ADCON RESULTS. ABOVE CONTROL NR

ASGND

BT

408/66

C09

M & M

A4C 148567

VA-112 3-66

8-12-66 299945

NNNN

ZC461XDGA929VBA655

RR RUCKDG

DE RUWJDAA1078 2302344

ZNR UUUUU

R 181440Z

FM 832D ADIV CANNON AFB NMEX

TO RUWDAF/BUWEPs FLT READ REP PAC NAS NORTH IS SANDIEGO CALIF

INFO RUCKDG/NAV AVIA SAF CTR NAS NORFOLK VA

RUWSAL/ATKRON ONE ONE TWO NAS LEMOORE CALIF

RUWDAK/CAR AIR WING ELEVEN NAS MIRAMAR CALIF

RUWSAA/NAS ALAMEDA ALAMEDA CALIF

RUWDAF/COM NAVAIR PAC NAS NORTH IS SANDIEGO CALIF

RUWSAA/COMMFAIR ALA NAS ALAMEDA ALAMEDA CALIF

RUWJFNA/NAVAL WEAPONS EVAL FACIL KIRTLAND AFB NMEX

BT

UNCLAS OS 08397 AUG 66. SENIOR MBR NAVY A/C ACCIDENT
BOARD SENDS.

PRIORITY DIR-REQUEST.

A. OPNAV INST P3750.6E.

1. IN ACCORDANCE PARA 38B REF A REQ PRIORITY DIR J65 ENGINE
SER NO 612332 INVOLVED VA-112 AAR SER 3-66A.

2. ENGINE LOCATED CANNON AFB, CLOVIS NMEX.

3. PHOTOS, STATEMENTS PERTINENT TO ACCIDENT INVESTIGATION
TO BE FWD'D SEPARATE COVER.

BT

461/66

COG M+M

FUL

A4C 148567

VA-112 3-66

8-12 18/4482

NNNDGB260VBA874

PP RUCKDG

DE RUWJFNA1148 2282359

ZNR UUUUU

P 162303Z

FM CO USNWEF KIRTLAND AFB ALBU NMEX

TO RUWJFNA/COMMANDANT EIGHTH NAVAL DISTRICT NEW ORLEANS LA

RUWSC/COMMANDER ATTACK CARRIER AIR WING ELEVEN

RUWJDAA/CANNON AFB NMEX

RUWSC/ATTACK SQUADRON ONE ONE TWO

INFO RUCKDG/NAVAL AVIATION SAFETY CENTER NAVAL AIR STATION NORFOLK VA

BT

UNCLAS

AIRCRAFT ACCIDENT INVESTIGATION

A. CONEIGHT 160143Z

1. CDR (b)(6), USN APPOINTED SR MBR ACCIDENT BOARD PER REF A TO INVESTIGATE VA-112 AAR SER 3-66A.

2. REQUEST LT (b)(6) CVW-11 FLT SURGEON/LCDR (b)(6) CVW-11 SAFETY OFFICER PROCEED ASAP CANNON AFB FOR INVESTIGATION AS ACCIDENT BOARD MEMBERS. ALSO REQUEST SVCS OF ENGINE/AIRFRAME REP.

3. FOR CANNON AFB, REQUEST BILLETING 5 OFFICERS, 3 ENL FOR ABOUT 3 DAYS PURSUANT TO INVESTIGATION. PLAN ARR CANNON 170930 LOCAL. PLAN

PAGE 2 RUWJFNA1148 UNCLAS

CONTACT CANNON SAFETY OFFICER 17 AUG FOR SUPPORT OF INVESTIGATION. REQMTS FOR VEHICULAR TRANSP INCLUDE TRIPS TO AND FROM SITE. MELO SERVICES, PHOTOGRAPHER, CLERICAL ASSISTANCE, AND ASSISTANCE IN INTERVIEW OF WITNESSES IF ANY ALSO POSSIBLE REQMT.

BT

Log: AI

EK,

NNNN

Orig:

162303Z

AVC 148567

VA-112 3-66

8-12-66

NNNNHSBEA

N

UJ&DGB 857VBC558

PP RUCKDG

DE RUWTFMA 7158 2280239

ZNR UUUUU

P R 160143Z AUG 66

FM COMEIGHT

TO RUWJFNA/NAVWEPEVACFAC KIRTLAND AFB ALBUQ NMEX

INFO RUWSC/COMATKCARAIRWING ELEVEN

RUWSC/ATKRON ONE ONE TWO

RUCKDG/NAVAL AVIATION SAFETY CENTER NORVA

RUWDAF/COMNAVAIRPAC

RUECM/NAVAIRSYS COMHQ

RUWSAA/COMFAIRALAMEDA

RUCKDA/COMNAVAIRLANT

RUEGHF/CNARESTRA

RUECM/CHNAVMAT

RUWDKC/BUWPSREP LONG BEACH

RUEGUC/BUWPSREP WOODRIDGE NEW JERSEY

RUEGHL/NAS DAL TEX

BT

UNCLAS

AIRCRAFT ACCIDENT BOARD

A. COMATKCARAIRWING ELEVEN 151710Z

B. ATKRON ONE ONE TWO 130712Z (PASEP)

1. REQUEST YOU TAKE REF A FOR ACTION. REFERENCE B ALSO APPLIES.

DIRECT LIAISON AUTHORIZED WITH ALL ACTIVITIES CONCERNED.

BT

67/66

Coq: AI

A4C 148567 VA 112 3-66

Aug.
8-12-66 160143Z

#24

NNNNDGB 685CBD851
PP RUCKDG
DE RUWDAK 238 2271710
ZNR UUUUU ZFD
P R 151710Z AUG 66
FM COMATKCARAIRWING ELEVEN
TO RUWTFMA/COMEIGHT
INFO RUCKDG/NAVAL AVIATION SAFETY CENTER
RUECM/CHNAVMAT
RUWDAF/COMNAVAIRPAC
RUCKDA/COMNAVAIRLANT
RUWSAA/COMFAIRALAMEDA
RUECM/NAVAIRSYSCOMHQ
RUEGHF/CNARESTRA
RUWJFNA/NWEF KIRTLAND AFB
RUEGHL/NAS DALLAS
RUWDKM/NAVPLANTREP LONG BEACH
RUEGUC/BUWEPSREP WOODRIDGE NEW JERSEY
RUWSAL/COMFAIRDET LEMOORE
RUWSAL/ATKRON ONE ONE TWO
BT
UNCLAS
AIRCRAFT ACCIDENT INVESTIGATION
A. OPNAVINST 3760.6E

#24

COG: Records
A.I.

PAGE TWO RUWDAK 238 UNCLAS

B. VA-112 130712Z AUG 66

C. MY 150241Z AUG 66

1. CANCEL MY 150241Z. REQUEST COMEIGHT ASSIGN RESPONSIBILITY FOR INVESTIGATION VA-112 AAR SER 3166A.

2. LCDR (b)(6), CVW-11 SAFETY OFFICER, AND LT (b)(6) CVW-11 FLIGHT SURGEON AVAILABLE THROUGH VA-112 AT NAS LEMOORE FOR BOARD ASSIGNMENT.
BT

#06

AVC 148567

VA-112

3-CC

8-12-CC 151710Z

15 AUG 66 03 20z
HAG 1000000

DVPXDGES 29 CBH 182
PP RUCKDG
DE RUWDAK 225 2270241
ZNR UUUUU
P R 150241Z AUG 66
FM COMATKCARAIRWING ELEVEN
TO RUWSAA/COMFAIRALAMEDA
INFO RUCKDG/NAVAVNSAFECEN
RUWDAF/COMNAVAIRPAC
RUECM/NAVAIRSYSOMHQ
RUCKYJ/COM EIGHT
RUCKDA/COMNAVAIRLANT
RUEGHF/CNARESTRA
RUECM/CHNAVMAT
RUWDKC/BUWPSREP LBEACH
RUEGUC/BUWPSREP WOODRIDGE NEW JERSEY
RUWSAL/COMFAIRDET LEMOORE
RUWSAL/ATKRON ONE ONE TWO

NASC

P

Aug A.I

BT

UNCLAS

AIRCRAFT ACCIDENT BOARD

A. OPNAVINST 3760.6E

B. VA-112 130712Z AUG 66 NOTAL

1. REQUEST CFAA ASSIGN RESPONSIBILITY FOR INVESTIGATION VA-112 AAR
SER 3-66A.

2. LCDR (b) (6), CVW-11 SAFETY OFFICER, AND LT (b) (6), CVW-11 FLIGHT
SURGEON, AVAILABLE AT NAS LEMOORE FOR BOARD ASSIGNMENT.

BT

10m

A4C 148567

VA-112 3-66

8-13 150241Z
66 Aug

DGB235 CBD023

PP RUCKDG
DE RUWSAL 009 2250709
ZNR UUUUU
P R 130712Z AUG 66
FM ATKRON ONE ONE TWO
TO RUECM/CNO
INFO RUECM/NAVAL AVIATION SAFETY CENTER
RUWDAF/COMNAVAIRPAC
INFO RUECM/NAVAIRSYSCOMHQ
RUCKYJ/COM EIGHT
RUWDAK/COMATKCARAIRWING ONE ONE
RUWSAA/COMFAIRALAMEDA
RUCKDA/COMNAVAIRLANT
RUEGHE/CNARESTRA
RUECM/CHNAVMAT
RUWSC/READATKCARAIRWING FOUR
RUWDAK/READATKCARAIRWING ONE TWO
RUHLBP/CG FMFPAC
RUCKHD/CG FMFLANT
RUHLHL/CINCPACFLT
RUWDKC/BUWEPREP LONG BEACH
RUEGUC/BUWEPREP WOODRIDGE NEW JERSEY
RUECW/JAG

PAGE TWO RUWSAL 009 UNCLAS
RUWJABA/DIRECTOR AEROSPACE SAFETY, NORTON AFB
BT
UNCLAS FOR OFFICIAL USE ONLY
PRELIMINARY & SUPPLEMENTARY MESSAGE REPORT OF AIRCRAFT ACCIDENT
A. OPNAVINST 3750.6E
1. A4C, 148567, ATKRON ONE ONE TWO, VA-112 SER 3-66A, ALVIS
2. FILED IFR NAS LEMOORE, CALIF TO DYESS AFB, TEXAS. 2.2 HRS TIME
IN FLIGHT
3. 130057Z, 18 NM WEST OF CANNON AFB, NEW MEXICO. AIRCRAFT
WRECKAGE LOCATED 20 NM NORTH OF CANNON AFB
4. ALFA DAMAGE

NASC

AAR

A4C 148567

VA 112

3-66

12-66 AUG
8-~~12~~ 130712Z

5. AIRCRAFT CRUISING AT FL330, ALL INSTRUMENTS NORMAL. ENTERED AREA OF LIGHT PRECIPITATION AND TURBULENCE. PILOT HEARD SQUEAL ORIGINATING AFT OF COCKPIT, BUILDING IN INTENSITY FOR APPROX ONE MINUTE. FOLLOWED BY MILD, MUFFLED EXPLOSION SOUND WHICH SEEMED TO COME FROM NOSE AREA. EGT AND RPM INDICATED ZERO. EMERGENCY GENERATOR DEPLOYED AND GLIDING DESCENT MADE TO VFR CONDITIONS AT FL250. PILOT ATTEMPTED AIRSTART AT FL200 AND 15,000 FEET, BOTH UNSUCCESSFUL. FUEL FLOW INDICATED 1500 PPH AFTER ENGINE FAILURE; NO CHANGE WITH THROTTLE MOVEMENT, INCLUDING OFF. PILOT IN CONTACT WITH ATC

PAGE TWO RUWSAL 009 UNCLAS

ENTIRE TIME. SUCCESSFUL EJECTION UTILIZING FACE CURTAIN AT 8,000 FEET, NORMAL SEQUENCE, SUSPECT EITHER AIR CONDITIONER TURBINE FAILURE WITH FOD INGESTED IN ENGINE OR BEARING FAILURE. OIL PRESSURE STEADY AT 34 PSI PRIOR TO ENGINE FAILURE.

6. JOHN HUBBARD ALVIS, CDR, (b)(6), USN, (b)(6), ACTIVE DUTY
NO INJURY

7. WEATHER 25,000 FEET OVERCAST, 90 DEGREES, DEWPOINT UNK, VIS 20 MILES, WIND UNK

8. NO KNOWN OR SUSPECTED MAINTENANCE OR INSPECTOR FACTORS

9. NECESSITY FOR DIR WILL BE DETERMINED AFTER PRELIMINARY INVESTIGATION

10. ROCKET EJECTION SEAT UTILIZED, MK 86 MOD 0 HARNESS RELEASE, MK 0 MOD 1 CATAPULT EJECTION NORMAL IN ALL RESPECTS

11. NO INJURIES TO CIVILIAN PERSONNEL

12. PROPERTY DAMAGE TO OPEN CULTIVATED FIELD

13. ENGINE J35 - 110A, SER NO. 612332

BT


NNN